

Checked mags and preflight every thing was good. Took off and flew for 30 minutes with no problem and started to develop engine trouble with sputtering and loss of RPM to about 2200RPM. Called Darrell and he told me to bring the plane back to the field. I flew the plane back to LS09 taking 15 minutes holding 400 alt and 2200 RPM. As I went to land, I realized I was fast and high so I tried a go around but lost power so I slipped to slow and tried to land. I was still fast and rolled past the runway into a ditch.

Matthew Leggett

8/24/20

