



RECORD OF INTERVIEW

Michael J. Folkerts
Aviation Accident Investigator
Central Region

NTSB Accident Number: CEN21FA360

Mr. Kreg Anderson was the airport manager at Chandler Field Airport (AXN) and flew the pilot's last flight review on October 30, 2020. He provided the following information:

- On the afternoon of the accident, he reported the pilot's stepson fueled the airplane.
- Based on records from the self-serve fuel pump, the airplane was fueled 27.38 gallons.
- The pilot had several family members at his cabin and was flying his stepson and stepson's wife from AXN to Flying Cloud Airport (FCM) so they could rendezvous with an airline flight at Minneapolis Airport (MSP).

- Mr. Anderson conducted a flight review with the pilot on October 30, 2020.
- The flying portion of the flight review lasted 1 hour (this flight review was recorded in the pilot's logbook).
- Only visual procedures were flown during the flight, with no instrument procedures flown.
- He stated that the visual flight procedures were flown satisfactorily.
- He described the pilot as very safety conscious and detail oriented, and that he enjoyed describing the aircraft's systems.
- Mr. Anderson was not aware of a safety pilot who flew with the pilot during the 6 months prior to the accident.