



Memorandum for Record

Fabian Salazar
Air Safety Investigator
National Transportation Safety Board
Investigator in Charge

NTSB Accident Number: WPR20LA238
Aircraft Registration & Make/Model: N7677C / Piper PA-32R-300
Accident Location: West Jordan, Utah
Accident Date: July 25, 2020

An autopsy of the pilot was performed by the Office of the Medical Examiner, Taylorsville, Utah 84129. The cause of death was listed as blunt force injuries.