



Memorandum for Record

Fabian Salazar
Air Safety Investigator
National Transportation Safety Board
Investigator in Charge

NTSB Accident Number: WPR22FA361
Aircraft Registration & Make/Model: N74349 / Grumman AA5B
Accident Location: Sahuarita, AZ
Accident Date: September 28, 2022

An autopsy of the pilot was performed by the Pima County Office of the Medical Examiner, Tucson, Arizona. The cause of death was listed as thermal injuries and probable blunt force injuries.