



Memorandum for Record

Fabian Salazar
Air Safety Investigator
National Transportation Safety Board
Investigator in Charge

NTSB Accident Number: WPR22LA130
Aircraft Registration & Make/Model: N101YY / Paradise Aircraft USA P1
Accident Location: Glendale, AZ
Accident Date: 3/19/2022

In a postaccident examination of the airplane's fuel tanks, the recovery agent, under supervision of the IIC, drained the remaining fuel from the wing tanks. The left tank drained less than one cup of fuel into a plastic container. The right tank drained less than a quarter gallon of fuel into the plastic container. Combined, there was less than one quarter gallon of fuel drained from both tanks. Figure 1 is a photo of the fuel drained from the tanks.



Figure 1. Photo showing the fuel drained into a one-gallon plastic container.