

MEMORANDUM FOR RECORD

Timothy W. Monville Sr. Air Safety Investigator Eastern Region

Date: 4/11/2023

NTSB Accident Number: ERA23FA033

An autopsy of the left and right front seat pilots was performed by Office of the Chief Medical Examiner, Concord, New Hampshire. The cause of death for both pilots was inhalation of smoke and toxic products of combustion.