

Memorandum For Record

Timothy W. Monville Sr. Air Safety Investigator Eastern Region

Date: March 30, 2021

NTSB Accident Number: ERA19FA210

Medical and Pathological Information:

An autopsy of the flightcrew was performed by the "Rand" Pathology Laboratory, Nassau, Bahamas. The cause of death for both was, "Blunt Force Trauma to Head, Neck and Torso."

According to the NTSB Survival Factors investigator all passengers sustained blunt force injuries during the impact with the water. Autopsies revealed that all seven occupants had serious traumatic brain injuries, and all sustained multiple other serious injuries including lacerations to one or more major organs such as the lungs, liver, kidneys, and spleen.