



Motor Carrier Attachment 13:

Qualcomm Screen Shot for Accident Driver

Cranbury, NJ; 06/07/2014

HWY14MH012

(2 pages)

Regionalized Dispatching System - A - [Outgoing Message]

File Dispatch Equipment QBC Tools Preferences Reports Window Help



Message Data Call Broadcast

Outgoing Msg TS: 6/6/2014 22:21:33

Service Co Code: WM

Tractor ID: 02568

Outgoing Msg Subj: TRIP MOVEMENT

Outgoing Msg Text:

TRIPMOVE : 6 9 1 7 0 1 6 2,MOVE,2 ORIGIN : STORE2068 DEST : MORTON SALT CITY :
 PERTH AMBOY STATE : NJ SCHEDULED DELV TIME : NONE PROJECTED ETA :
 06/09/2014 07:30 ETA HOURS : 11.0 DISTANCE : 43.17 TRANSIT TIME HOURS : 1
 TRANSIT TIME MIN : 1 COMMENT : NJ TURNPIKE TO X 10 FOLLOW SIGNS FOR 440 TOWARDS
 PERTH AMBOY/WOODBRIDGE TAKE 440 TO LAST NJ X (HIGH ST / STATE ST). AT THE SPLIT STAY
 RIGHT ONTO 611N. TURN RIGHT AT THE NEXT LIGHT. FOLLOW THE ROAD UNDER THE BRIDGE

Last Change Userid wabdali

Srvc Co Code	Tractor Id	Dom. ID	Outgoing Msg Ts	Subject	Seq	Processed	Re Re
WM	02568	7834	6/6/2014 04:16:49	ACCIDENT	1	Y	Y
WM	02568	7834	6/6/2014 09:16:19	Rte 33S In PA.	1	Y	Y
WM	02568	7834	6/6/2014 18:38:35	TRIP MOVEMENT	1	Y	Y
WM	02568	7834	6/6/2014 22:21:33	TRIP MOVEMENT	1	Y	Y
WM	02568	7834	6/6/2014 22:21:33	TRIP MOVEMENT	2	Y	Y
WM	02568	7834	6/7/2014 06:10:43	CANCEL MOVE 3	1	Y	Y
WM	02568	7834	6/7/2014 06:36:47	Accident on NJT	1	Y	Y

Select

Cancel

Insert

Save

Delete

Close

Sort

Print

51

ver. 3.5