

**NATIONAL TRANSPORTATION SAFETY BOARD
RELEASE OF WRECKAGE**


ACCIDENT/INCIDENT
IDENTIFICATION NUMBER
WPR22FA361

PART I - RELEASE OF WRECKAGE

REGISTERED OWNER (name and address) Barton G. Prieve Aurora, CO. 80014		REGISTRATION OR IDENTIFICATION NUMBER N74349
		MAKE Grumman American Aviation
MODEL AA5B	DATE OF ACCIDENT/INCIDENT September 28, 2022	LOCATION Sahuarita, AZ.

The National Transportation Safety Board has has not completed its investigation of the wreckage described above. All wreckage except that listed on the reverse side is hereby released to the registered owner, or owner's representative, for appropriate disposition. (If no parts are retained, insert NONE.)


NONE

SIGNATURE OF NTSB REPRESENTATIVE 	TITLE Air Safety Investigator	DATE May 25, 2023
---	---	-----------------------------

(This section may be signed by a person, not the owner or owner's representative, who has knowledge of the disposition of the wreckage and its parts. Such signature does not place responsibility for disposition of the wreckage upon that person.)

I HEREBY ACKNOWLEDGE:

- Receipt of the above described wreckage.
- Removal of the parts, if any, listed on the reverse side of this form.

SIGNATURE 	TITLE Aviation Surveyor McLarens General Aviation	DATE 5/25/23
--	---	------------------------

REMARKS:

NATIONAL TRANSPORTATION SAFETY BOARD
RECEIPT OF PARTS

ACCIDENT/INCIDENT
IDENTIFICATION NUMBER
WPR22FA361

PART II - RELEASE OF PARTS

REGISTRATION NUMBER N74349	MAKE Grumman American Aviation	MODEL AA5B
-------------------------------	-----------------------------------	---------------

DATE OF ACCIDENT/INCIDENT September 28, 2022	LOCATION Shaurita, AZ.
---	---------------------------

The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components listed below. When the examination is complete, they will be returned to:

OWNER OR OWNER'S REPRESENTATIVE -

Air Transport

ADDRESS

Phoenix, AZ 85009

PARTS, PIECES, OR COMPONENTS RETAINED:

- 1. Section of Aileron control cable.

SIGNATURE OF NTSB REPRESENTATIVE	TITLE Air Safety Investigator	DATE May 25, 2023
----------------------------------	----------------------------------	----------------------

The registered owner or owner's representative will acknowledge receipt of the materials by signing this form in the spaces designated

SIGNATURE OF OWNER OR OWNER'S REPRESENTATIVE	TITLE	DATE
ADDRESS		