

CORPORATE HEADQUARTERS 3799 West Airline Hwy.-P.O. Drawer 536 Reserve, LA 70084-0536 985-536-0445

SOLD TO

CMI SHIP MANAGEMENT 4770 BISCAYNE BLVD PENTHOUSE C MIAMI FL 33137

SHIP TO

M/V VICTORY II

PORT GENERATOR

CHARLESTON, SC

INVOICE NUMBER	INVOICE DATE	CUSTOMER I	10	CUSTOMER C	RDER NUMBER		STORE	DIV	SALESMAN	TERMS	PAGE
W44C7521468	02-13-20	F140205		-E-2020			44	E	EXX	1	1
PSO/WO NO	DOC DATE	PC LC	MC]		SHIP VIA					INV SEQ N	3
4426293	01-02-20	14 10	10								6184
MAKE MODI	EL I	SERIAL N	IMBER	EQ.	UIPMENT NUMB	ER	METER F	READING		MACH ID NO	
AA 3516		N00184		•	ICTORY			26.	. 0		
QUANTITY	ITEM	N/R		DESCRIPTION			UNIT	PRICE		EXTENSION	

TEST ENGINE START-UP

COMPLAINT: PERFORM TEST RUN ON ENGINE.

CAUSE: AS PER CUSTOMER'S REQUEST.

CORRECTION: 1/6/20 TO 1/8/20 TRAVELED TO TEST RAN ENGINE TO CUSTOMER CHARLESTON, SC. SATISFACTION AND FOUND NO LEAKS OR ISSUES. SAVED ALL DATA AND SET HOURS AND FUEL BURN TO ZERO. TESTED OIL PRESSURE SHUTDOWN, HIGH COOLANT TEMPERATURE SHUTDOWN, AND OVERSPEED AT 75 PERCENT OF RATED SPEED AND FOUND ALL SHUTDOWNS WERE WORKING PROPERLY.

COMMENT: FOUND #2 EXHAUST SENSOR READING ERRATIC. REPLACED WITH NEW UPDATED SENSOR AND TEST RAN. FOUND ALL OPERATIONS NORMAL.

1 2 4	5N-2126 161-9926 267-6532 383-2990 1PU3000M	ADAPTER SENSOR GP-PR TOWELS SENSOR GP-TE SHIELD SP	5 5 5 5 5	8.95 169.95 6.11 387.14 6.85	35.80 169.95 12.22 1548.56 13.70
		TOTAL PARTS		SEG. 01	1780.23

TERMS: *-NOT RETURNABLE

UNLESS NOTED-CORES ARE DUE BACK WITHIN 60 DAYS FOR CREDIT CONSIDERATION.

We cannot accept parts returned without our permission unless returned within 20 days. All parts non returnable to the factory are non returnable to us. Our responsibility ceases when shipment has been delivered in good order to transportation company. If the shipment arrives in bad order, have receipt noted by carriers agent. Claims for concealed shortages and/or damages will not be considered unless made in 15 days after receipt of shipment. Any changes in part numbers have been made to insure your receiving the latest improved parts, entirely interchangeable with those ordered, and there is a 5% special handling charge on a I nonstok items. Notice: In consideration of credit extended for this purchase I (we) hereby agree to pay you for same at your office in Reserve, La. on your established terms, and to pay service charge at the current rate for all invoices not paid within 30 days of invoice date until paid. Further, in the event it becomes necessary to refer this invoice to an attorney for collection, I agree to pay 25% attorneys fees and court costs.

PAY THIS AMOUNT	CONT'D
AMOUNT CREDIT (DO NOT PAY)	

** ALL AMOUNTS PAYABLE IN US DOLLARS ** ALL BILLS PAYABLE AT P.O. BOX 54942, NEW ORLEANS, LA. 70154