

Cawthra Joshua

From: Ryan Lloyd [REDACTED]
Sent: Tuesday, August 10, 2021 2:03 PM
To: Cawthra Joshua
Subject: Re: WPR21LA261

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

The drifting began immediately once the airplane touched down and roll began.

Ryan

From: Cawthra Joshua [REDACTED]
Sent: Tuesday, August 10, 2021 1:58 PM
To: Ryan Lloyd [REDACTED]
Subject: RE: WPR21LA261

Thanks Ryan.

Question, when the airplane began to drift left, do you recall when this happened during the landing roll? Was it at the time of touchdown, or about how far/long into the landing roll?

Josh

Joshua Cawthra
Senior Aviation Accident Investigator
National Transportation Safety Board
[REDACTED]
Federal Way, WA 98001

[REDACTED]

From: Ryan Lloyd [REDACTED]
Sent: Tuesday, August 10, 2021 1:56 PM
To: Cawthra Joshua [REDACTED]
Subject: Re: WPR21LA261

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

See attached for statement.

V/r,