



RECORD OF CONVERSATION

Eleazar Nepomuceno
Air Safety Investigator
General Aviation Accident Division

Date: 7/24/2020
Person Contacted: Hao Lin (student pilot)
NTSB Accident Number: WPR20CA209

Narrative:

The following is a synopsis of the information provided by the student pilot on this date:

- The radio was not properly working during his solo flight, so he switched to radio 2, then returned to the departure airport for a precautionary landing instead of following his original flight plan.
- The pilot added that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.