



RECORD OF CONVERSATION

Eleazar Nepomuceno
Aviation Accident Investigator
Western Pacific Region

Date: July 7, 2021
Person Contacted: Lawrence Allen
NTSB Accident Number: WPR21LA275

Narrative:

The following is a synopsis of the information provided by the pilot on this date:

The pilot reported that after landing on runway 35 at OGD, Ogden, Utah, he made a right turn, high-speed exit onto taxiway "ALPHA". Subsequently, the airplane ground looped to the right, which caused the left wing to drag across the taxiway. A post-accident exam revealed that the left wing and elevator sustained substantial damage. The pilot reported that there were no preimpact mechanical failures or malfunctions to the airplane.