

## RECORD OF INTERVIEW

Daniel P. Boggs Air Safety Investigator National Transportation Safety Board Office of Aviation Safety - Eastern Region

Date: 8/12/2020 @1000EDT

Person Interviewed: Richard Oliver - Pilot

NTSB Case Number: ERA20CA282

## **Narrative:**

Mr. Richard Oliver was interviewed by telephone.

Richard stated that during landing, he was flying slow due to the short runway. During landing, the airplane bounced, and a gust of wind blew him to the left side of the runway. Richard stated he was having problems getting the airplane to settle back down on the runway and he was afraid to give the airplane any throttle since he was being blown off to the left side. The airplane then contacted some tree's and they egressed out the door.

Richard Oliver stated the was no mechanical issues with the airplane.