

# **ATTACHMENT 1**

## **AIRWORTHINESS GROUP FACTUAL REPORT**

**NTSB No. ANC20MA010**

**Record of Conversation – Safari Director of Maintenance  
(1 Page)**

# Record of Conversation

Saturday, January 4, 2020 12:30 PM

---

<b>Interview:</b>	Paul Collins (Safari Helicopters DOM)
<b>Phone:</b>	██████████
<b>Location:</b>	Telephone Conversation

---

## Narrative:

The following is a summary of conversation with Mr Paul Collins, the Director of Maintenance for Safari Helicopters.

Mr Collins said that he had reviewed the maintenance records and that there is no record entry of the video equipment being removed. He said that he knows that the other mechanic employed by Safari had removed the recorder from the aft baggage compartment, and that the only item that remained installed was the camera located in the nose of the helicopter. The work was done but neither the other mechanic or he himself entered the work into the logbooks.

Van S. McKenny IV  
Aerospace Engineer (Helicopters)  
Western Pacific Region