



Survival Factors Attachment 10

Master CAD Log

**Cranbury, NJ
HWY14MH012**

(17 Pages)

Consolidated CAD log Entries

Time	Agency	Source	unit	Dis-patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:00:44 AM	NJSP	NJSP CAD									Vehicle overturned, people stuck inside
1:00:52 AM	NJSP	NJSP CAD									response created
1:02:01 AM	NJSP	NJSP CAD	5905	5905							
1:02:03 AM	NJSP	NJSP CAD	5905		5905						
1:02:05 AM	NJSP	NJSP CAD									response acknowledgement from 5905
1:02:50 AM	NJSP	NJSP CAD									wrecker request
1:03:49 AM	NJSP	NJSP CAD									Mercer Co notified, sending FD and BLS
1:04:03 AM	mercero	created									
1:04:13 AM	NJSP	NJSP CAD									Towing notified
1:04:32 AM	NJSP	NJSP CAD									medical request
1:04:35 AM	NJSP	NJSP CAD									fire request
1:05:09 AM	NJSP	NJSP CAD	7116	7116							
1:05:11 AM	NJSP	NJSP CAD	7116		7116						
1:05:16 AM	NJSP	NJSP CAD									response acknowledgement from 7116

Time	Agency	Source	unit	Dis-patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:05:56 AM	Hightstown	House 715 Cranbury Twp	Station 41	Station 41							
1:05:57 AM	Hightstown FD	House 715 Cranbury Twp	C41	C41							
1:05:57 AM	Hightstown FAS	House 715 Cranbury Twp	A41-11	A41-11							
1:05:57 AM	Cranbury FAS	House 715 Cranbury Twp	A48-15	A48-15							
1:06:21 AM	NJSP	NJSP CAD	7116			7116					
1:06:52 AM	NJSP	NJSP CAD									ODU supervisor notification
1:07:01 AM	Hightstown FAS	House 715 Cranbury Twp	A41-12	A41-12							
1:07:10 AM	Hightstown FAS	House 715 Cranbury Twp	A41-12		A41-12						
1:07:15 AM	Hightstown FAS	House 715 Cranbury Twp	A41-11				A41-11				
1:07:20 AM	NJSP	NJSP CAD									left and center lanes down, need heavy towing
1:07:22 AM	NJSP	NJSP CAD	5905			5905					
1:07:35 AM	NJSP	NJSP CAD									right lane partially down also

Time	Agency	Source	unit	Dis- patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:07:47 AM	Hightsto wn FD	House 715 Cranbury Twp	C41	C41							
1:07:53 AM	Hightsto wn FD	House 715 Cranbury Twp	C41		C41						
1:07:58 AM	NJSP	NJSP CAD									vehicles traveling on right shoulder
1:09:14 AM	RWJUH EMS	Capital Health	MR6	MR6							
1:09:16 AM	RWJUH EMS	Med Central 038389	MR3	MR3							
1:09:20 AM	Cranbury FAS	Capital Health	A48- 14	A48-14							
1:09:38 AM	RWJUH EMS	Med Central									etrapment - unknown patients
1:10:12 AM	NJSP	NJSP CAD									3 entrapped males
1:10:22 AM	RWJUH EMS	Med Central 038389	MR3		MR3						
1:10:42 AM	NJSP	NJSP CAD									3 intrapped males in van with minor injuries
1:11:22 AM	NJSP	NJSP CAD	7026	7026							
1:11:24 AM	NJSP	NJSP CAD	7026			7026					
1:11:27 AM	NJSP	NJSP CAD	6482	6482							
1:11:28 AM	NJSP	NJSP CAD	6482		6482						
1:11:33 AM	NJSP	NJSP CAD									response acknowledgement from 6482

Time	Agency	Source	unit	Dis- patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:11:34 AM	Cranbury FD	House 715 Cranbury Twp	E48-1		E48-1						
1:11:53 AM	NJSP	NJSP CAD									passenger van overturned
1:12:05 AM	NJSP	NJSP CAD									mercerc co notified for ALS
1:12:56 AM	Cranbury FAS	House 715 Cranbury Twp	A48- 15		A48-15						
1:13:09 AM	Cranbury FAS	Capital Health	A48- 15	A48-15							
1:13:12 AM	Cranbury FAS	Capital Health	A48- 15		A48-15						
1:13:17 AM	RWJUH EMS	Capital Health	MR6		MR6						
1:13:21 AM	NJSP	NJSP CAD									fatal accident unit
1:13:27 AM	Hightsto wn FD	House 715 Cranbury Twp	E41	E41							
1:13:27 AM	NJSP	NJSP CAD									crime scene request
1:13:34 AM	Hightsto wn FD	House 715 Cranbury Twp	R41		R41						
1:13:39 AM	Cranbury FAS	Capital Health	A48- 14				A48-14				discontinued because another unit was closer
1:13:42 AM	Hightsto wn FD	House 715 Cranbury Twp	Station 41					Station 41			

Time	Agency	Source	unit	Dis-patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:13:47 AM	Hightstown FD	House 715 Cranbury Twp	Station 41				Station 41				
1:14:14 AM	NJSP	NJSP CAD									ODU supervisor notification
1:14:24 AM	Hightstown FD	House 715 Cranbury Twp	C41			C41					
1:14:66 AM	Cranbury FD	House 715 Cranbury Twp	E48-1			E48-1					
1:15:08 AM	Hightstown FD	House 715 Cranbury Twp	E41	E41							
1:15:10 AM	NJSP	NJSP CAD									3 entrapped, 2 serious, 1 appears to be fatal, can't get to him - FD on scene
1:15:21 AM	NJSP	NJSP CAD	4975	4975							
1:15:22 AM	Hightstown FD	House 715 Cranbury Twp	E41		E41						
1:15:24 AM	NJSP	NJSP CAD	4975			4975					
1:15:28 AM	Cranbury FAS	House 715 Cranbury Twp	A48-15			A48-15					
1:15:37 AM	Hightstown FAS	House 715 Cranbury Twp	A41-12			A41-12					
1:15:46 AM	Cranbury FAS	Capital Health	A48-15			A48-15					

Time	Agency	Source	unit	Dis- patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:17:04 AM	Hightsto wn FD	House 715 Cranbury Twp	C41								C41 going in service with tools
1:20:27 AM	RWJUH EMS	Med Central 038389	MR3			MR3					
1:21:05 AM	NJSP	NJSP CAD									aviation request
1:21:58 AM	Hightsto wn FD	House 715 Cranbury Twp	R41			R41					
1:22:38 AM	NJSP	NJSP CAD	5907	5907							
1:22:39 AM	NJSP	NJSP CAD	5907			5907					
1:22:41 AM	NJSP	NJSP CAD	6482			6482					
1:22:44 AM	NJSP	NJSP CAD									response acknowledgement from 5907
1:22:44 AM	NJSP	NJSP CAD									CSI notified and enroute (7038)
1:22:49 AM	NJSP	NJSP CAD									national union fire insurance co
1:23:11 AM	NJSP	Capital Health	South star	Southstar							
1:23:36 AM	RWJUH EMS	Capital Health	MR6			MR6					
1:23:39 AM	Hightsto wn FD	House 715 Cranbury Twp	E41			E41					
1:24:45 AM	NJSP	NJSP CAD									Southstar ETA 14 min

Time	Agency	Source	unit	Dis- patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:24:54 AM	NJSP	NJSP CAD									supervisor on scene
1:25:15 AM	Capital Health EMS	Capital Health	Southstar		Southstar						
1:26:14 AM	NJSP	NJSP CAD									2 subjects need to be flown, possible 3rd
1:26:31 AM	RWJUH EMS	Med Central 038389	MR6	MR6							
1:26:41 AM	NJSP	NJSP CAD									fire request
1:26:51 AM	NJSP	NJSP CAD									ODU supervisor notification
1:26:52 AM	RWJUH EMS	Med Central 038389	MR6		MR6						
1:27:27 AM	Hightsto wn FD	House 715 Cranbury Twp	C41								C41 requested air medevac
1:27:44 AM	NJSP	NJSP CAD									mercero sending fire truck to helipad for assistance
1:28:53 AM	Cranbury FD	House 717 Cranbury Twp	statio n 48	station 48							
1:31:06 AM	NJSP	NJSP CAD									driver of 2005 Nissan Identified
1:31:19 AM	RWJUH EMS	Med Central									medevac approx 15 min ETA
1:31:44 AM	NJSP	NJSP CAD									insurance info
1:31:48 AM	NJSP	NJSP CAD	6651	6651							

Time	Agency	Source	unit	Dis- patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:31:49 AM	NJSP	NJSP CAD	6651		6651						
1:32:24 AM	NJSP	NJSP CAD									policy number
1:33:08 AM	NJSP	NJSP CAD									all lanes are closed
1:34:29 AM	NJSP	NJSP CAD									1 subject fatal, no pulse, can't confirm, 2 subjects serious, cranbury station notified
1:34:42 AM	Hightstown FD	House 715 Cranbury Twp	C41								C41 requested 2 additional BLS
1:35:15 AM	Capital Health EMS	Capital Health	monroe BLS	monroe BLS							
1:35:15 AM	Capital Health EMS	Capital Health	A146-1	A146-1							
1:35:45 AM	Monroe Twp	Monroe Twp									call taken
1:36:51 AM	Monroe Twp	Monroe Twp									1 BLS requested
1:36:57 AM	Cranbury FD	House 717 Cranbury Twp	station 48				station 48				
1:37:02 AM	NJSP	NJSP CAD	5911	5911							
1:37:04 AM	E. Windsor FD	House 717 Cranbury Twp	station 46	station 46							

Time	Agency	Source	unit	Dis- patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:37:04 AM	NJSP	NJSP CAD	5911			5911					
1:38:55 AM	Hightsto wn FD	House 715 Cranbury Twp	Station 41								Station 41 milestone Patient Extricated
1:39:01 AM	Hightsto wn FD	House 715 Cranbury Twp	Station 41								station 41 2nd patient extricated
1:39:12 AM	hightsto wn FD	House 715 Cranbury Twp									Station 41 milestone modified to extrication started
1:39:23 AM	Monroe Twp	Monroe Twp									2nd BLS requested
1:39:26 AM	Monroe Twp	Monroe Twp	U501	U501							
1:39:34 AM	hightsto wn FD	House 715 Cranbury Twp									station 41 milestone correction of extrication started to time 1:17 am
1:40:00 AM	NJSP	NJSP CAD									response acknowledgment from 7026
1:40:04 AM	RWJUH EMS	Med Central									Monroe sending 2 BLS at request of ALS on scene
1:40:35 AM	RWJUH EMS	Med Central									Northstar 5 min ETA
1:42:07 AM	RWJUH EMS	Med Central									Monroe 501 and 508, Mercer Co sending East Windsor BLS
1:42:15 AM	E. Windsor FD	House 717 Cranbury Twp	E46-1	E46-1							
1:42:17 AM	RWJUH EMS	Med Central 038389	MR6			MR6					

Time	Agency	Source	unit	Dis-patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:42:18 AM	E. Windsor FD	House 717 Cranbury Twp	C46	C46							
1:42:21 AM	E. Windsor FD	House 717 Cranbury Twp	c46		c46						
1:42:23 AM	E. Windsor FD	House 717 Cranbury Twp	E46-1		E46-1						
1:42:26 AM	E. Windsor FD	House 717 Cranbury Twp	Station 46				Station 46				
1:43:17 AM	NJSP	NJSP CAD									northstar is flying, not southstar
1:43:32 AM	Monroe Twp	Monroe Twp	U508	U508							
1:43:41 AM	Monroe Twp	Capital Health	monroe BLS		monroe BLS						
1:44:38 AM	NJSP	NJSP CAD									northstar can take 2, they need additional 2 flown
1:45:53 AM	NJSP	NJSP CAD									northstar sending 2nd helicopter for other 2 subjects
1:47:08 AM	Monroe Twp	Monroe Twp	U508			U508					
1:47:16 AM	Monroe Twp	Monroe Twp	U501			U501					
1:47:34 AM	E. Windsor FD	House 717 Cranbury Twp	C46			C46					
1:47:38 AM	RWJUH EMS	Capital Health	MR3								

Time	Agency	Source	unit	Dis- patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:47:40 AM	hightsto wn FAS	House 715 Cranbury Twp	A41- 12								A41-12 arrived at helipad
1:47:40 AM	RWJUH EMS	Capital Health	MR3								
1:47:43 AM	RWJUH EMS	Capital Health	MR3								
1:48:14 AM	NJSP	Capital Health	Southstar			southstar					discontinued because another unit was closer
1:48:44 AM	NJSP	Capital Health	Southstar			Southstar					
1:48:44 AM	NJSP	Capital Health	North	North							
1:48:50 AM	NJSP	Capital Health	North				North				
1:49:04 AM	NJSP	Capital Health	North star	Northstar							
1:49:07 AM	NJSP	Capital Health	Northstar		Northstar						
1:49:10 AM	NJSP	Capital Health	Northstar			Northstar					
1:50:50 AM	NJSP	NJSP CAD	6509	6509							
1:50:51 AM	NJSP	NJSP CAD	6509		6509						
1:53:25 AM	E. Windsor Twp	Capital Health	A146- 1		A146-1						
1:53:32 AM	Monroe Twp	Capital Health	monroe BLS			monroe BLS					

Time	Agency	Source	unit	Dis-patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:54:36 AM	E. Windsor Twp	House 715 Cranbury Twp	A146- 1	A146-1							
1:54:39 AM	E. Windsor Twp	House 715 Cranbury Twp	A146- 1		A146-1						
1:54:49 AM	NJSP	NJSP CAD									5911 make one pronouncement on scene
1:55:02 AM	E. Windsor FD	House 717 Cranbury Twp	E46-1			E46-1					
1:56:24 AM	NJSP	NJSP CAD	6651			6651					
1:56:34 AM	Monroe Twp	Monroe Twp	U508								enroute to landing strip
1:57:19 AM	cranbury FAS	House 715 Cranbury Twp	A48- 15						A48-15		
1:58:37 AM	Monroe Twp	Monroe Twp	u501				u501				
1:58:52 AM	NJSP	NJSP CAD									7026 transporting 2 back to cranbury station
1:58:56 AM	RWJUH EMS	Med Central									Duplicate call of incident 038389
1:59:06 AM	Monroe Twp	Monroe Twp	U501								enroute to RWJUH
1:59:23 AM	E. Windsor Twp	Capital Health	A146- 1				A146-1				
1:59:32 AM	NJSP	NJSP CAD									5911 requesting ME

Time	Agency	Source	unit	Dis- patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
1:59:41 AM	RWJUH EMS	Med Central 038392	MR6								DOA - no treatment
2:00:29 AM	NJSP	NJSP CAD									5911 pronouncement made at 1:53 by Physician at RWJUH
2:00:55 AM	NJSP	NJSP CAD									7026 22 Station
2:04:10 AM	NJSP	NJSP CAD									Fatal accident notification to LT
2:04:12 AM	NJSP	NJSP CAD									second helicopter 10 minutes out
2:05:22 AM	NJSP	NJSP CAD									first helicopter enroute with one
2:05:26 AM	NJSP	NJSP CAD	6091	6091							
2:05:30 AM	NJSP	NJSP CAD	6499	6499							
2:06:13 AM	NJSP	NJSP CAD									ME notified
2:08:19 AM	NJSP	NJSP CAD									driver of Limo Van at police station
2:09:09 AM	E. Windsor Twp	House 715 Cranbury Twp	A146- 1				A146-1				
2:10:36 AM	Hightsto wn FD	House 715 Cranbury Twp		C41							requested ME
2:13:48 AM	NJSP	NJSP CAD	6091			6091					
2:14:50 AM	Monroe Twp	Monroe Twp	u508				u508				
2:15:23 AM	Monroe Twp	Monroe Twp	U508								enroute to RWJUH

Time	Agency	Source	unit	Dis-patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
2:16:34 AM	Monroe Twp	Capital Health	monroe BLS				monroe BLS				
2:16:50 AM	NJSP	Capital Health	Northstar				Northstar				
2:16:55 AM	E. Windsor FD	House 717 Cranbury Twp	C46				C46				
2:16:56 AM	NJSP	NJSP CAD									monroe FAS will transport 2nd person due to long ETA for Helicopter
2:16:57 AM	E. Windsor Twp	House 717 Cranbury Twp	E46-1					E46-1			
2:17:07 AM	NJSP	NJSP CAD									second helicopter cancelled
2:17:39 AM	RWJUH EMS	Capital Health	MR3								
2:18:39 AM	RWJUH EMS	Capital Health	MR6				MR6				
2:20:16 AM	NJSP	NJSP CAD	6509	6509							
2:20:18 AM	NJSP	NJSP CAD	6509			6509					
2:21:32 AM	Cranbury FAS	House 715 Cranbury Twp	A48-15							A48-15	
2:21:35 AM	Cranbury FAS	House 715 Cranbury Twp	A48-15				A48-15				
2:24:47 AM	NJSP	NJSP CAD	5951	5951							

Time	Agency	Source	unit	Dis- patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
2:24:51 AM	NJSP	NJSP CAD	5951		5951						
2:25:25 AM	NJSP	NJSP CAD									4975 out at Cranbury station
2:26:05 AM	NJSP	NJSP CAD	6499		6499						
2:27:05 AM	NJSP	NJSP CAD	6595	6595							
2:27:08 AM	NJSP	NJSP CAD	6595			6595					
2:27:23 AM	Hightsto wn FD	House 715 Cranbury Twp	E41					E41			
2:27:53 AM	hightsto wn FAS	House 715 Cranbury Twp	A41- 12	A41-12							
2:27:57 AM	hightsto wn FAS	House 715 Cranbury Twp	A41- 12				A41-12				
2:31:24 AM	E. Windsor FD	House 717 Cranbury Twp	E46-1				E46-1				
2:34:48 AM	RWJUH EMS	Med Central 038389	MR3				MR3				
2:35:29 AM	NJSP	NJSP CAD									Woman at station
2:38:12 AM	hightsto wnd FD	House 715 Cranbury Twp	E41				E41				
2:40:03 AM	NJSP	NJSP CAD									driver of Buick at station

Time	Agency	Source	unit	Dis- patched	Enroute	On Scene	Available	returning	Trans- porting	at hospital	Description
2:40:20 AM	NJSP	NJSP CAD	5951			5951					
2:42:29 AM	NJSP	NJSP CAD									truck driver at station
2:46:56 AM	cranbury FAS	Capital Health	A48- 15				A48-15				
2:52:06 AM	RWJUH EMS	Med Central 038389	MR3								call cleared
3:31:35 AM	RWJUH EMS	Med Central 038389	MR6								call cleared
4:11:48 AM	Hightsto wn FD	House 715 Cranbury Twp	C41								ME on scene
4:32:16 AM	Hightsto wn FD	House 715 Cranbury Twp	R41					R41			
4:43:34 AM	Hightsto wn FD	House 715 Cranbury Twp	R41				R41				
4:46:31 AM	Hightsto wn FD	House 715 Cranbury Twp	C41				C41				
4:46:48 AM	Hightsto wn FD	House 715 Cranbury Twp	C41								no further services needed
4:48:34 AM	Cranbury FD	House 715 Cranbury Twp	E48-1					E48-1			
4:54:35 AM	Cranbury FD	House 715 Cranbury Twp	E48-1				E48-1				