

**SUMMARY OF DAMAGED CABLE**

CABLE TYPE	LENGTH IN FEET	COST (\$)	LEAD TIME (DAYS)	NOTES
BHA-PVBN/2C2.5RE	884			
BHA-PVPN/12C1.5RE	2635			
BHA-PVPN/24C1.5RE	1705			
BVA-PVXD/2C2.5BK	180			
BVA-PVXN/2C1.5BK	482			
BVA-PVXN/2C16BK	150			
BVA-PVXN/2C2.5BK	9037			
BVA-PVXN/2C25BK	220			
BVA-PVXN/2C6BK	330			
BVA-PVXN/2C95BK	165			
DVA-PFVN/2C10BK	30			
RRA-PVBN/2C2.5RE	550			
BVA-PFXN/3C25BK	545			
BVA-PFXN/4C95BK	49			
BVA-PFXN/1C95BK	264			
BVA-PFXN/3C50BK	590			
BVA-PFXN/4C2.5BK	1200			
BVA-PFXN/3C95BK	387			
BVA-PFXN/3C70BK	500			
DVA-PFXN/7C1.5BK	4661			
ESA-DEXD/2P1.5BK	305			
BVA-PFXN/3C2.5BK	3732			
BVA-PFXN/3C4BK	1478			
DVA-PVXN/12C2.5BK	438			
BVA-PFXN/3C6BK	640			
BVA-PFXN/3C10BK	1095			
BVA-PFXN/3C35BK	632			
FSC GLOBAL SM000022	3280			
BVA-CBTD/7C1.5BK	180			
Summit FM2xAAH FLEX 2x2x0.5	750			
Belden 8267	315			
PANDUIT PSM7004BUKEM	10438			
ESA-DEXD/8P.75RE	609			
ESA-DEXD/1P.75RE	1493			
Belden FD3B006CB	4465			
Belden 1300SB	1135			
DVA-PFXN/14C1.5BK	180			
BVA-PFXN/3C1.5BK	150			
BHA-PFPN/3C2.5RD	500			
LAPP 2170279	3585			
BVA-PFXD/4C1.5BK	320			
DFA-PFED/4C6BK	150			
DVA-PVXN/12C1.5BK	785			
ESA-DEXD/1P1.5RE	125			
RCA-DEXD/2P1.5BK	250			
RCA-PFXN/2P1.5BK	1491			
RCA/PFNX/8P0.75BK	150			
ESA-PFBN/2P2.5BK	210			
ESA-PFXN/1P1.5BK	1042			
ESA-PFXN/2P1.5BK	2840			
RCA-PFXN/16P1.5BK	4940			
ESA-PFXN/2P0.75BK	150			
RCA-PFXN/2P0.75BK	120			
RCA-PFXN/1P0.75BK	115			
RCA-PFXN/1P1.5BK	1400			
FLA-DEYN/8P1.5BK	332			
RCA-PFXN/4P1.5BK	600			
BHA-PVPN/2C4RE	700			
DVA-PFXN/10C1.5BK	300			
RSA-PFXN/4P1.5BK	795			
BVA-PVXN/2C4BK	323			
ESA-PFXN/4P1.5BK	170			
BHA-PVPN/2C16RE	350			
<b>Grand Total</b>	<b>77622</b>			