

Manufacturing Timeline of Incident Aircraft

2023

March 24

MED Plug Manufactured by Spirit Malaysia

MAR

MAY

May 10

MED Plug Received in Wichita

August 20

Fuselage Shipped from Spirit Wichita

AUG

August 31

Fuselage Arrived in Renton

September 5

Boeing Verified Spirit's Pre-Rigging of MED Plug

September 7

Boeing Documented Door Surround Rivets Not Replaced

September 18

MED Plug Opened by Boeing, Arrestor Bolts Removed

September 1

Boeing Authors Non-Conformance Report for 5 Door Surround Rivets

September 6

Spirit Contractor Documented Removal and Replacement of 5 Door Surround Rivets

September 8

Spirit / Boeing Disagreement on Door Surround Rivets Non-Conformance (NTSB Exhibits 11B,11C)

September 19

Door Surround Rivets Replaced By Spirit Contractor

OCT

October 31

Aircraft Delivered to Alaska Airlines