

March 29, 2020

Dear Sirs,

This is to inform you of an accident happening on Saturday, March 27, 2020. During a regular landing in my pasture the wind caught the helicopter causing it to drift into my fence. When the skid caught on the fence it flipped over onto my driveway. Please contact me if you need further information.

Sincerely,

Billy Helvey



March 30, 2021

Gerald A. Dotson

ASI/PMI (Airworthiness)

North Texas Flight Standards District Office, SW19

8700 Freeport Pkwy, Suite 225

Irving, TX 75063

[REDACTED]

Reference: Requested Statement

Mr. Dotson, on March 29th, 2021 I was a passenger in helicopter tail number 1045C. As we were doing a normal landing in a low grass pasture it appeared the wind caught the helicopter and turned it to the right and the landing gear caught the fence from what I can tell and turned the aircraft on its side. If you have further questions, please feel free to give me a call.

Very Best,


[REDACTED]

Billy (William) Moss