

[REDACTED]

From: [REDACTED]
Sent: Tuesday, September 19, 2023 10:05 AM
To: [REDACTED]
Subject: Time line of events

For information the Y394 typically works the West end of the A yard and reports to the West end eastbound Shanty. On this day we could not fill the Y397 so the job was moved to the East end of the eastbound due to heavy switching. This is a one man RCO job.

Y39416 timeline of events

Employee: [REDACTED]

On duty at 2359 reporting to the East end eastbound shanty.

Switch list issued on E00 at 2342/16

Employee on the power and performs tests 0018/17 / 0023/17

0025/17 1st move on locomotives

0056/17 ties onto E00 track

0059/17 Pulls out 18 cars from the E00 track

0116/17 Finished 18 cars

0127/17 ties onto E00 track

0131/ Pulls out 14 cars from E00 track

0151/Switches 11 of the 14 cars out of E00

0205/0250 Gets E06 track together with the head 3 cars out of E00 and shoves track to the West end

0255/17 ties onto E00 track

0259/17 pulls 22 cars out of E00 track

0303/17 Ties onto 1 car in the clear in E14 track and now has ahold of 23 cars total.

0304/0320 shoves 23 cars to the West end of E14 track.

0321/17 begins East bound after cutting off cars in E14. Now has light power coming East

0324/17 Incident occurs