



**VEHICLE FACTORS GROUP CHAIRMAN'S FACTUAL REPORT
ATTACHMENT**

2001 Ford Excursion Limousine Re-Certification Invoice

Schoharie, New York

HWY19MH001

(3 pages)

AI LIMO DEPOT DOT FACILLITY

5670 MERRICK ROAD
 MASSAPEQUA N.Y 11758
 516 826-4040
 516 826-3434

Estimate

Date	Estimate #
2/9/2010	5157

Name / Address
ROYALE LIMOSINE 518 286 4444 FAX 518 426 4609 5580644000032021 EX 0310 SEC 001 DON 12210

P.O. No.	Terms	Due Date	Rep	Account #	FOB	Project
		2/9/2010				
Item	Description	Qty	Total			
PARTS	2001 EXCURS EMAIL. INFO@ALBANYCARSERVICE.COM					
PARTS	PARTS RADIOUS ARMS 2	2	310.00T			
PARTS	PART UPPER BALL JOINTS 2	2	198.00T			
PARTS	PART LOWER BALL JOINTS 2	2	130.00T			
PARTS	PARTS SWAY BAR BUSHINGS	2	72.00T			
PARTS	PARTS E BRAKE CABLE WITH ADJUSTER		0.00			
PARTS	PARTS 1 LICENSE PLATE LITE FOR BUMPER		110.00T			
COMPLY FOR DOT	WITH NEW MANUFACTURIN FROM AILIMO DEPOT		27.00T			
MATERIALS	MATERIALS WITH LABOR RECARPET COMPLETE CAR		2,400.00T			
PARTS	PARTS 1 ROLL MATT FOR OTHER EXCURSION		1,900.00T			
PARTS	PARTS 1 TEMPLETE FOR EXCURSION HERE AND MAKE A ROLL MATT		530.00T			
LABOR	LABOR RADIOUS ARMS LEFT AND RIGHT SIDE	6	570.00T			
LABOR	LABOR REMOVE Y PIPE TO REPAIR EXHAUST LEAK PROPERLY WITH NEW GASKETS and reinstall with new hardware		225.00T			
PARTS	PARTS 1 HEAD LITE 4007 INSTALLED WITH REMOVAL OF HEADLAMP'S AND CORNER LIGHTS FOR PARKING LITES		98.00T			
LABOR	LABOR INSTALL E CABLE WITH ADJUSTER		165.00T			
LABOR	LABOR BALL JOINTS LEFT AND RIGHTSIDE UPPERS AND LOWERS WITH SWAY BAR BUSHINGS	2	590.00T			
LABOR	LABOR RADIOUS ARMS LEFT AND RIGHT SIDE		395.00T			
MATERIALS	MATERIALS 30 FEET OF OF 1 BY 2 10 GAUGE					
LABOR	LABOR CUT AND INSTALL ALL STEEL FOR CHASI SUPPORTS WITH GUSSITS LEFT AND RIGHT SIDE ONLY		1,200.00T			
Subtotal						
Sales Tax (8.625%)						
Total						

A1 LIMO DEPOT DOT FACILLITY

5670 MERRICK ROAD
 MASSAPEQUA N.Y 11758
 516 826-4040
 516 826-3434

Estimate

Date	Estimate #
2/9/2010	5157

Name / Address
ROYALF LIMOSINE 518 286 4444 FAX 518 426 4609 5580644000032021 EX 0310 SEC 001 DON 12210

P.O. No.	Terms	Due Date	Rep	Account #	FOB	Project
		2/9/2010				
Item	Description				Qty	Total
LABOR	LABOR INSTALL 6 SUPPORTS TO COACH PANELS INSTEAD OF 12					1,200.00T
LABOR	LABOR WELD IN SEAT SUPPORTS PROPERLY N/C					0.00T
LABOR	LABOR REUSE BODY BUSHINGS WITH SPACERS 12					0.00T
	SIDE COACH PANELS ARE BOWING OUT DO TO CHASI SUPPORTS ARE N/G					
	WITH OUT TAX APPROX 10,720					
Subtotal						\$10,720.00
Sales Tax (8.625%)						\$924.60
Total						\$11,644.60