



**VEHICLE AND SURVIVAL FACTORS ATTACHMENT 6 – SAN MATEO FD
INCIDENT REPORT**

Mountain View, CA

HWY18FH011

(4 pages)

Incident History for: #BFS180870041 Xref: #FMA180870003

Case Numbers: \$BFS1800003595 \$FMA1803280005

Received 03/28/18 19:01:29 BY FBU1/DGR
Entered 03/28/18 19:04:28 BY FBU1/DGR Receive to Entry 00:02:59
Dispatched 03/28/18 19:04:29 BY FIR2/BKS
Enroute 03/28/18 19:06:03 Dispatch to Enroute 00:01:34
Onscene 03/28/18 19:08:52 Dispatch to Onscene 00:04:23
Closed 03/28/18 22:01:40

Initial Type: VF Final Type: HMC (HAZARDOUS MATERIAL - CONSULT)
Initial Priority: 1 Final Priority: 1
Initial Alarm Level: 1 Final Alarm Level: 1
Disposition: HM Source: 9 Primary Unit: HM33 R/P Contact:
Police BLK: 10121 Fire BLK: 10121 EMS BLK: 10121
Group: SMF (SMO/SMF/EMS) Beat: FS24 Map Page: 729:A7 Fire Map Page: 2352
Exception list #: Exception Resp Zone: BU
Loc: 24 S AMPHLETT BLVD ,SMO btwn CYPRESS AV & 2ND AV (V)
Loc Info: ATLAS TOWING/YARD TRO
Name: JESUS Addr: [REDACTED] Phone: [REDACTED]

/190428 (DGR) ENTRY TESLA CAR SMOKING / BATTERIES EXPLODING

/190429 (BKS) DISP E24 #E24 ENGINE 24
#S25809 KELLY TREVOR CAPT S/O
#S25808 FLORES, JUAN
#S28336 VARVEL, VICTORIA

/190429 FROM [FS24]

/190504 (DGR) SUPP TXT: NOT THREATENING ANYTHING

/190603 (BKS) #ENROUT E24

/190603 \$ASNCAS E24 \$BFS1800003595

/190645 (DGR) SUPP TXT: RP ADV THIS IS VEH IS THERE AS EVIDENCE A
ND FIRE DEPT HAD PLACED IT AWAY FROM OTHER VEH
'S AND BLDG BECAUSE IT KEEPS SETTING ITSLF ON
FIRE

/190852 (BKS) #ONSCNE E24

/191347 ASSTOS BC5 [24 S AMPHLETT BLVD ,SMO]
#BC5 BC5 PAGER
#BC6 BC6 PAGER
#F82044 GOODWIN, CHUCK BC

/191347 (*****) FROM [FS23]

/191347 (BKS) ASSTOS CM21X1 [24 S AMPHLETT BLVD ,SMO]

/191347 \$ASNCAS CM21X1 \$FMA1803280005

/191347 (*****) FROM [ZCE2]

/191529 (BKS) NEWLOC CM21X1 [AMPHLETT]

/192345 AOS E24
/192357 ONSCNE E24
/192416 ASSTOS TAC25 [24 S AMPHLETT BLVD ,SMO]
/192416 (*****) FROM [ZCE1]
/192946 (BKS) SUPP TXT: BC5 REQ CALL FROM CHP - STORED VEH FOR EV
IDENCE
/193002 SUPP TXT: CHP OS
/193148 SUPP TXT: HMC REQ PER BC5
/193151 BALNCE TYP: VF --> HMC
RSP: 001 --> 056
PRI: 1 --> 1
LVL: 1 --> 1
/193159 ASST HM14 #BL140 CURTIS, DAN CAPT
#BL330 WAY, MARK CAPT
#BL279 REARDON, SEAN FF
#BL210 MACFARLAND, CHRIS FF
#BLHMAT HAZMAT GROUP
/193159 FROM [FS14]
/193303 SUPP TXT: REQ HM14 LL BC5 - NUMBER IN SCRATCH
/193325 MANACK HM14
/193400 NEWLOC BC5 [IC]
/193510 (SXC) SUPP TXT: HM15 REQ'ING PAGE OUT ENV HEALTH [REDACTED]
[REDACTED]
/193852 SUPP NAM: HM15,
TXT: FOR VF
/194011 CROSS #FMA180870003
/195159 (JRL) SUPP TXT: JRL ADVISING PD / REQ PW TO THE SCENE
/195242 (KYC) SUPP TXT: HM14 PROVIDED ALT PH# FOR CONTACT: [REDACTED]
[REDACTED]
/200053 (DGR) SUPP TXT: PER ERICK PW/ENR 30 MIN
/200230 (SXC) SUPP ,I/C COPIED PW ETA
/200237 CLEAR HM14 ,PER E153
/201021 (BKS) ASST SMFINV [24 S AMPHLETT BLVD ,SMO]
#SMFINV SMF INVESTIGATOR ALL PAGE
#TEMP TEMP, ID NOT IN SEC FILE
/201021 (*****) FROM [FS21]
/201108 (BKS) SUPP TXT: REQ SMFINV CALL BC5 ON CELL IN SCRATCH
/201302 \$PREMPT SMFINV
/201302 \$ASSTER PR5E #S28295 ZAMBRANA, MIKE
/201302 PREDSP SMFINV PR5E
/201937 ASSTER HM33 [24 S AMPHLETT BLVD ,SMO]
#HM33 JENSEN, DIRK ENVHEL
/201937 (*****) FROM [FS99]
/202007 (BKS) SUPP TXT: HM33 ETA 35 MIN

/202755 (KYC) PREMPT PR5E ,ADVD VLL NOT ACTUALLY RESPONDING.. CALLED BY
BC5 FOR CONSULT
/203703 (BKS) ASSTOS TO5 [24 S AMPHLETT BLVD ,SMO]
#S25919 COOK, ROBERT CAP/MED
/203703 (*****) FROM [FS23]
/205439 (BKS) ONSCNE HM33
/211754 (KYC) SUPP TXT: HAVE SMO PD SGT CALL BC5
/211958 MISC BC5 ,SMO PD ADVD
/214940 CLEAR TO5
/215041 #AOR E24
/215119 AOS BC5
/215247 SUPP TXT: PER CMD21 TRAFFIC, HM33 WILL BE CLEARING
SHORTLY
/215429 CLEAR CM21X1
/215429 CLEAR TAC25
/215626 #AOR BC5
/220140 (SXC) CLEAR HM33 DSP: HM
,VIA LL
/2