

Unusual Occurrence Reports for 2/6/2025

Train#	Delay	Status	Delay Code	Details
Total Annulments:			0	
Total Partially Annulled:			0	
Total Delays:			10	
<hr/>				
Report #:	53947			Recorded by: kuc
Location:	Iron Interlocking			
Incident:	Catenary Power Loss			
Train:	Consist:			
Crew data:				
Remarks:	5:48p- Temporary catenary power loss Iron Interlocking to West Trenton Yard, trains 306 and 3545 were in the affected area; Power Dept re-energized the catenary trains are inspecting pantographs.			
Cause:				
<hr/>				
Report #:	53948			Recorded by: kuc
Location:	Baldwin			
Incident:	Fire under train			
Train:	3223	Consist: 132		
Crew data:				
Remarks:	6:14p- 3223 mu 132 stopped south of Crum Lynne Station at Baldwin INT reporting fire under the train. Crew has lowered the pantograph and moved all passengers to the rear of the train. Roberts Mechanical has been notified and is enroute. TMs have been notified and enroute. 7241 is stopped in the station at Crum Lynne.			
	6:18p- TM F. Scheib is enroute to the location at Baldwin. Fire Dept is on location.			
	6:19p- TM T. Williams is enroute to assist with 3223.			
	6:23p- Bus control was contacted and bus has been ordered for unknown number of passengers.			
	6:25p- Roberts Yard has been called to order a diesel.			
	6:36p- Wilmington/ Newark Line has been suspended due to fire activity south of Crum Lynne Station.			
	6:38p- 3223 evacuated 325 passengers with Ridley Park. Police are on location.			
	6:42p- 3223 passengers are off the trains and are walking via the street to Crum Lynne Station.			
	6:47p- TM T. Williams on location and has been named OSC. Train 7241 with 225 passengers, 9225 120 passengers. Amtrak ET is enroute to the location.			
	7:03p- 9862 CC-RY, 9863 RY-CW, 2528 WIL-CC annulled due to crews out of place on the Wilmington Line.			
	7:14p- EMS on location attending to a passenger from 3223 due to possible asthma attack.			
	7:38p- Dart has been contacted to assist with transporting passengers from Claymont to Newark Stations.			
	8:12p- System Safety J. Townsend is on location at 3223.			
	8:13p- AD S. Williams and Dir. M. Sceno are on location at 3223.			

Unusual Occurrence Reports for 2/6/2025

8:16p- Per OSC T. Williams 9225 evacuated all their passengers as of 8:13p with no incident.

9:55p - Power has been restored to the line. Fire Dept has cleared the scene. Mechanical is working on getting the cars running. The ACS64 set will operate north back to Phil.

10:08pm - Train 5239 will go through to Wilmington tonight. D9266 will serve as a passenger extra inbound from Wilmington. CCIM and announcers notified.

1:51am- Amtrak reports the catenary has been inspected and ok for normal operation.

2:20am- TM Williams reports MU 132 started smoking again at Prospect Park . Fire Dept has been dispatched.

2:43am- Fire Department on location and have extinguished the smoldering. Mechanics will continue to prep the equipment to get it back to WECY.

3:26am- TM Williams reports the train is now on the move north out of Prospect Park enroute to WECY.

3:58am- All tracks on the Wilmington line have officially reopened with no restrictions.

Cause:

Train#	Delay	Status	Delay Code	Details
1226 S		A	MM	ANNULLED AT NEWARK DUE TO FIRE ACTIVITY SOUTH OF CRUM LYNNE
P 2528 N	12		MM	PROTECTED OUT OF 30TH ST
2528 S		P	MM	ANNULLED AT CRUM LYNN DUE TO DISABLED 3223 AT BALDWIN INT
2530 S		A	MM	ANNULLED AT NEWARK DUE TO FIRE ACTIVITY SOUTH OF CRUM LYNNE
* 3223 S		P	M	PARTIALLY ANNULLED FROM CRUM LYNNE TO NEWARK DUE TO FIRE UNDER TRAIN
* 5227 S		A	MM	ANNULLED FROM CENTER CITY TO NEWARK DUE TO FIRE ACTIVITY SOUTH OF CRUM LYNNE
5229 S			MM	ANNULLED FROM CENTER CITY TO WILMINGTON DUE TO FIRE ACTIVITY SOUTH OF CRUM LYNNE
5231 S			MM	ANNULLED FROM CENTER CITY TO MARCUS HOOK DUE TO FIRE ACTIVITY SOUTH OF CRUM LYNNE
* 7241 S		P	MM	PARTIALLY ANNULLED FROM CRUM LYNNE TO WILMINGTON DUE TO FIRE ACTIVITY SOUTH OF CRUM LYNNE
* 9225 S		P	MM	PARTIALLY ANNULLED FROM CRUM LYNNE TO NEWARK DUE TO FIRE ACTIVITY SOUTH OF CRUM LYNNE

Unusual Occurrence Reports for 2/6/2025

Train#	Delay	Status	Delay Code	Details
9232 S		A	MM	ANNULLED FROM MARCUS HOOK TO SUBURBAN STATION DUE TO FIRE ACTIVITY SOUTH OF CRUM LYNNE
9250 S		A	MM	ANNULLED FROM NEWARK TO SUBURBAN STATION DUE TO FIRE ACTIVITY SOUTH OF CRUM LYNNE
9863 S		A	MM	ANNULLED FROM ROBERTS AVE YARD TO CHESTNUT HILL WEST DUE TO AMTRAK SUSPENSION OF THE WILMINGTON LINE
Total Annulments:			6	
Total Partially Annulled:			4	
Total Delays:			3	

Report #: 53949 Recorded by: kuc

Location: Roberts Ave Yard

Incident: Gas Smell

Train: Consist:

Crew data:

Remarks: 7:31p- Robert Yardmaster reported that Roberts Shop was evacuated due to smell of gas; Fire Dept is on location.

7:56p- Roberts Yardmaster reports that the Fire department has left Roberts Shop. No answer yet from the shop on the status.

Cause:

Report #: 53950 Recorded by: kuc

Location: Cornwells Heights

Incident: Equipment Issues

Train: 9761 Consist:

Crew data:

Remarks: 6:24p- 9761 stopped and setting up to operate other than leading end at Cornwells Heights to Trenton Station.

7:24p- 725 stopped at Trenton Station due to unable to take power from MU 113

Cause:

Train#	Delay	Status	Delay Code	Details
* 725 S	30		M	HELD AT CROYDON DUE TO EQUIPMENT ISSUES, ON TIME AT KAY
726 S		A	MM	ANNULLED FROM TRENTON DUE TO MECHANICAL ISSUES ON TURN TRAIN 9761
* 9761 S	57		M	HELD AT CORNWELLS HEIGHTS DUE TO EQUIPMENT ISSUES, 3 LATE AT KAY
Total Annulments:			1	
Total Partially Annulled:			0	
Total Delays:			2	
