



Airworthiness - Photo 20. Microscopic view of the vertical speed indicator face. Note needle slap mark is near the maximum indication of 2,000 feet per minute descent. (NTSB-Lab Polaroid)