

2/19/16



ENGINE COMPONENTS, INC.
San Antonio, TX 78217-5994

SERVICEABLE

FAA Certificated Repair Station NO. [REDACTED]

Item E225 CRANKSHAFT Serial Number 259

Mfg. TCM Part Number L45

Remarks	Polish <input checked="" type="checkbox"/> / Ground <input type="checkbox"/> Mains <u>STD</u>	Installed	<input checked="" type="checkbox"/> C/W TCM MSB 96-10
	Polish <input checked="" type="checkbox"/> / Ground <input type="checkbox"/> Pins <u>STD</u>	<u>NA</u> Sludge Tubes	<input type="checkbox"/> C/W Lyc SB 530
	Renitride to Specifications <u>NA</u>	<u>NA</u> Blade Bushings	<input type="checkbox"/> C/W Lyc SB 505
	Mag Particle & Dimensional Insp <u>IEA</u>	Oil Plug <u>NA</u>	<input checked="" type="checkbox"/> C/W Lyc SB 475
	Plated & Baked Flange	B/U C/W Assy IAW Mfg's	<input type="checkbox"/> C/W AD 97-26-17
	Final Inspection Satisfactory	SB # <u>71189-24</u>	<input type="checkbox"/> Dynamic Balance
	REPAIRED IAW MPP 9045		Per AMP4302

QAS993 Rev. 0 (07/12/01)

CUSTOMER'S OWN OIL PLUG, INSTALLED.

2/19/16

I certify that the repair made to the unit listed on the reverse side was made and inspected in accordance with current regulations of the FAA and the part is Airworthy and approved for return to service.

Signed _____

Date 25 FEB 2002

Details are on file at this Repair Station under Work Order No. 88585-01

*Please call for your copy of ECI's **Class Reference Manual™** or visit our web site at www.eci2fly.com for service instructions, class reference information and parts and service price lists.*

ENGINE COMPONENTS, INC.
SAN ANTONIO, TX 78217 5994

Page 1

PHONE: [REDACTED]

Order Number: 41683 Sold to: 109665
Order Date : 02/26/2002 AIR CARGO EXPRESS
Cust PO No. : C/O FRANCES DANIELS
Print Date : 02/26/2002 02:10 PM [REDACTED]
Printed by : LIW ANCHORAGE AK 99524
STATUS : OK

art #	Description	Qty	U/M
	CRANKSHAFT PLATE & POLISH	1.00	EACH
	CRANKSHAFT ULTRASONIC INSP.	1.00	EACH
	CRANKSHAFT PARTS	1.00	EACH
	COUNTER WEIGHT REBUSHED	1.00	EACH
	PARTS	1.00	EACH
	COUNTER WEIGHT REJECT	1.00	EACH
	MAGNAFLUX GEARS	1.00	HOURL
type E-225	88585-01C 88585-02C 88585-03C COUNTERWEIGHTS 639915	1.00	EACH

For Installation Eligibility and Continued Airworthiness
Instructions, refer to ECI's web site: www.eci2fly.com

** Northwest Aviation Conference & Trade Show-Puyallup, WA
** February 23-24, 2002

** Montana Aviation Conference - Bozeman, MT
** February 28 - March 2, 2002

Customer Service FAX [REDACTED]

SHIP TO: 109665 Ship Priority: 1
AIR CARGO EXPRESS Location : [REDACTED]
C/O FRANCES DANIELS Special Inst :
[REDACTED] Ship Via : UPS 2ND DAY STANDARD
ANCHORAGE AK 99519 Terms 6 : M/C-VISA
CR CARD : [REDACTED]
Reference # : 88585-01 From Fac: 1

Filed _____ Verified _____ Issued _____ Packaged [REDACTED] Shipped _____