

Fri, October 05, 2018 11:38:35 AM

## Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 09/15/2018    Inspected By: William Johnson  
Inspection Type: FRA Required    How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 09/15/2018 12:55:51 PM  
Date Inspection Closed by Inspector: 09/15/2018 12:55:51 PM

### Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
DENVER	LARAMIE SUB	LARAMIE SUB	4146 SIDE	03 103	528.55	529.52	No	ALLEN	HINKER	GRANITE SIDING
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 2		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 1		509.50	512.00	No	ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 1		545.58	547.29	No	ALLEN	HINKER	DALE JCT TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 1		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 2		509.50	512.00	No	ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 1		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 2		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 2		545.58	547.29	No	ALLEN	HINKER	DALE JCT. TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 2		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 1		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT

### Track Traversed Information

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 2		509.50	510.81		ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 1		510.89	512.00		ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 1		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 1		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 1		545.58	547.29	No	ALLEN	HINKER	DALE JCT TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 1		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE

Comments

### Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
LARAMIE SUB	LARAMIE SUB	4146 NO 1	538.13		127A2-127.A2 - Insufficient fas	Repaired Before Traffic	09/15/2018	Corr from Trk Mtce Plan	09/15/2018		

### Curves Walked

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 1		537.96	538.40	Allen	Hinker	BORIE TO DALE JCT

### Switch Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
LARAMIE SUB	LARAMIE SUB	4145 NO 2	514.46 514.47		133AE-133.A14 - Loose, worn or	Repaired Before Traffic	09/15/2018	Corr from Trk Mtce Plan	09/15/2018		

### Joint Bar Inspections

**No Joint Bar Inspections Found**

**TMP Joint Bar Re-Inspect**  
**No TMP Joint Bar Re-Inspect Records Found**



[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

**Top of Page**