



## Track Inspection & FRA Reports

Return To: [UP Employees Home](#)Logged In As: XXXXXXXXXX [Log Out](#)

Fri, October 05, 2018 12:14 52 PM

### Union Pacific Railroad FRA Track Inspection & Defect Report

**Inspection Date:** 09/21/2018    **Inspected By:** William Johnson  
**Inspection Type:** FRA Required    **How Conducted:** Hi-Rail Walk

Date Inspection Uploaded into the Central System: 09/21/2018 04:24:28 PM

Date Inspection Closed by Inspector: 09/21/2018 04:24:28 PM

#### Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
DENVER	LARAMIE SUB	LARAMIE SUB	4140 SIMN		99.92	103.16	No	ALLEN	HINKER	SPEER TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 2		509.50	512.00	No	ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 SIDE	03_103	528.55	529.52	No	ALLEN	HINKER	GRANITE SIDING
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 2		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 2		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 1		509.50	512.00	No	ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4138 SIDE	03_142	518.29	519.71	No	ALLEN	HINKER	SPEER CENTER SIDING
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 1		545.58	547.29	No	ALLEN	HINKER	DALE JCT TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 1		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 1		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 1		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 2		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4138 NO 4		518.27	519.76	No	ALLEN	HINKER	SPEER
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 2		545.58	547.29	No	ALLEN	HINKER	DALE JCT. TO HERMOSA

#### Track Traversed Information

DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 2		509.50	512.00	No	ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4138 NO 4		518.27	519.76	No	ALLEN	HINKER	SPEER
DENVER	LARAMIE SUB	LARAMIE SUB	4140 SIMN		99.92	103.16	No	ALLEN	HINKER	SPEER TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 2		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 2		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 1		545.58	547.29	No	ALLEN	HINKER	DALE JCT TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 2		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE

**Comments**

#### Track Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments

LARAMIE SUB	LARAMIE SUB	<u>4146</u> <u>NO 1</u>	539.42		127A2-127.A2 - Insufficient fas	Repaired Before Traffic	09/21/2018	Corr from Trk Mtce Plan	09/21/2018		
LARAMIE SUB	LARAMIE SUB	<u>4146</u> <u>NO 1</u>	540.13		127A2-127.A2 - Insufficient fas	Repaired Before Traffic	09/21/2018	Corr from Trk Mtce Plan	09/21/2018		

### Curves Walked

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
DENVER	LARAMIE SUB	LARAMIE SUB	<u>4146</u> NO 1		539.19	539.65	Allen	Hinker	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	<u>4146</u> NO 1		539.74	540.36	Allen	Hinker	BORIE TO DALE JCT

### Switch Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
LARAMIE SUB	LARAMIE SUB	<u>4135</u> <u>NO 2</u>	<u>510.72</u> 510.72		133A1-133.A18 - Obstruction in	Repaired Before Traff c	09/21/2018	Corr from Trk Mtce Plan	09/21/2018		

### Joint Bar Inspections

**No Joint Bar Inspections Found**

### TMP Joint Bar Re-Inspect

**No TMP Joint Bar Re-Inspect Records Found**



Top of Page