











Aviation Investigation Notification

Location: Houston, AK Accident Number: ANC24LA020

Date & Time:March 14, 2024, 16:30 LocalRegistration:N9041K

Aircraft: Stinson 108 Injuries: 2 Minor

Flight Conducted Under: Part 91: General aviation - Personal

The NTSB is conducting a <u>Class 4 investigation</u> into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:StinsonRegistration:N9041KModel/Series:108Aircraft Category:Airplane

Amateur Built:

Operator: On file Operating Certificate(s) None

Held:

Operator Designator Code:

Meteorological Information and Flight Plan

| Conditions at Accident Site: | VMC | Condition of Light: | Day |
|----------------------------------|------------------|------------------------------|-------------|
| Observation Facility, Elevation: | AWS,354 ft msl | Observation Time: | 03:56 Local |
| Distance from Accident Site: | 7 Nautical Miles | Temperature/Dew Point: | -9°C /-11°C |
| Lowest Cloud Condition: | Clear | Wind Speed/Gusts, Direction: | /, |
| Lowest Ceiling: | None | Visibility: | 10 miles |
| Altimeter Setting: | 29.65 inches Hg | Type of Flight Plan Filed: | None |
| Departure Point: | Houston, AK | Destination: | Skwetna, AK |

Wreckage and Impact Information

| Crew Injuries: | 1 Minor | Aircraft Damage: | Substantial |
|---------------------|---------|----------------------|--------------------|
| Passenger Injuries: | 1 Minor | Aircraft Fire: | None |
| Ground Injuries: | | Aircraft Explosion: | None |
| Total Injuries: | 2 Minor | Latitude, Longitude: | 61.599924,-149.805 |

Administrative Information

Investigator In Charge (IIC): Hill, Millicent

Additional Participating Persons: Robert Parsons; FAA/FSDO; Anchorage, AK

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Page 2 of 2 ANC24LA020