



Aviation Investigation Notification

Location:	Knoxville, TN	Accident Number:	ERA24LA155
Date & Time:	March 25, 2024, 19:49 Local	Registration:	N912GB
Aircraft:	SOUTH CENTRAL AVIATION SEAREY	Injuries:	1 Minor
Flight Conducted Under:	Part 91: General aviation - Personal		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	SOUTH CENTRAL AVIATION	Registration:	N912GB
Model/Series:	SEAREY	Aircraft Category:	Airplane
Amateur Built:			
Operator:	WILLIAMS MICHAEL V	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:		Condition of Light:	
Observation Facility, Elevation:	KDKX, 833 ft msl	Observation Time:	19:35 Local
Distance from Accident Site:	0 Nautical Miles	Temperature/Dew Point:	14°C / 2°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	/ ,
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	29.95 inches Hg	Type of Flight Plan Filed:	
Departure Point:		Destination:	Knoxville, TN

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	35.963833,-83.873667

Administrative Information

Investigator In Charge (IIC):	Rayner, Brian
Additional Participating Persons:	David Stamps; FAA FSDO; Nashville, TN
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.