



Aviation Investigation Final Report

Location: NEAR BARROW, Alaska Accident Number: ANC82DA097

Date & Time: September 23, 1982, 14:00 Local Registration: N21753

Aircraft: CESSNA 185 Aircraft Damage: Substantial

Defining Event: 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT FLEW TO A FISHING CAMP NEAR BARROW, AK. DURING THE LANDING ROLL, THE AIRCRAFT STRUCK A WET SNOW DRIFT (ABOUT 2FT. DEEP) AND FLIPPED OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA - SELECTED - PILOT IN COMMAND

2. (F) TERRAIN CONDITION - SNOW COVERED

3. (F) TERRAIN CONDITION - SNOWBANK

Occurrence #2: NOSE OVER

Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

Certificate:	Airline transport	Age:	54,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	July 1, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	30000 hours (Total, all aircraft), 250	0 hours (Total, this make and model)	

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N21753
Model/Series:	185 185	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	18503066
Landing Gear Type:	Tailwheel	Seats:	6
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	IO-520-D
Registered Owner:		Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 ANC82DA097

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	7 miles
Lowest Ceiling:	Overcast / 3000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	28°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	BARROW , AK (BRW)	Type of Flight Plan Filed:	VFR
Destination:	BARROW , AK (BRW)	Type of Clearance:	None
Departure Time:	13:15 Local	Type of Airspace:	

Airport Information

Airport:		Runway Surface Type:	Snow
Airport Elevation:	0 ft msl	Runway Surface Condition:	Snow
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	1500 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	71.280448,-156.779067(est)

Page 3 of 4 ANC82DA097

Administrative Information

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date: September 23, 1983

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=71846

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 ANC82DA097