



Aviation Investigation Final Report

Location: Panama City, Incident Number: DCA13WA097

Date & Time: May 22, 2013, 01:16 UTC Registration:

Aircraft Damage: Minor

Defining Event: Loss of control on ground **Injuries:** 90 None

Flight Conducted Under: Non-U.S., commercial

Analysis

Probable Cause and Findings

Findings

Factual Information

History of Flight

Landing-landing roll	Runway excursion
Landing-landing roll	Loss of control on ground (Defining event)

The Accident Investigation Unit (UPIA) of Panamá has notified the NTSB of an incident involving a B737-700 that occurred on May 22, 2013. The NTSB has appointed a U.S. Accredited Representative to assist the UPIA investigation under the provisions of ICAO Annex 13 as the State of Manufacturer and Design of the airplane.

All investigative information will be released by the UPIA.

Information

Certificate:	Age:
Airplane Rating(s):	Seat Occupied:
Other Aircraft Rating(s):	Restraint Used:
Instrument Rating(s):	Second Pilot Present:
Instructor Rating(s):	Toxicology Performed:
Medical Certification:	Last FAA Medical Exam:
Occupational Pilot:	Last Flight Review or Equivalent:
Flight Time:	

Page 2 of 5 DCA13WA097

Aircraft and Owner/Operator Information

Aircraft Make:		Registration:		
Model/Series:		Aircraft Category:		
Year of Manufacture:		Amateur Built:		
Airworthiness Certificate:		Serial Number:		
Landing Gear Type:		Seats:		
Date/Type of Last Inspection:		Certified Max Gross Wt.:		
Time Since Last Inspection:		Engines:		
Airframe Total Time:		Engine Manufacturer:		
ELT:		Engine Model/Series:		
Registered Owner:	COPA Airlines	Rated Power:		
Operator:		Operating Certificate(s) Held:	None	

Meteorological Information and Flight Plan

The state of the s			
Conditions at Accident Site:		Condition of Light:	
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	
Destination:		Type of Clearance:	
Departure Time:		Type of Airspace:	

Page 3 of 5 DCA13WA097

Wreckage and Impact Information

Crew Injuries:	N/A	Aircraft Damage:	Minor
Passenger Injuries:	90 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	90 None	Latitude, Longitude:	

Page 4 of 5 DCA13WA097

Administrative Information

Investigator In Charge (IIC): Ward, Effie Lorenda

Additional Participating
Persons:

Original Publish Date: November 3, 2020

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=87045

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 DCA13WA097