



Aviation Investigation Notification

| | | | |
|--------------------------------|--------------------------------------|-------------------------|------------|
| Location: | Marietta, TX | Accident Number: | CEN21LA077 |
| Date & Time: | December 5, 2020, 13:30 Local | Registration: | N371MP |
| Aircraft: | ROBINSON HELICOPTER COMPANY R44 II | Injuries: | 5 None |
| Flight Conducted Under: | Part 91: General aviation - Personal | | |

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

| | | | |
|----------------------------------|-----------------------------|---------------------------------------|------------|
| Aircraft Make: | ROBINSON HELICOPTER COMPANY | Registration: | N371MP |
| Model/Series: | R44 II II | Aircraft Category: | Helicopter |
| Amateur Built: | | | |
| Operator: | Private Individual | Operating Certificate(s) Held: | None |
| Operator Designator Code: | | | |

Meteorological Information and Flight Plan

| | | | |
|---|-----------------|-------------------------------------|------------------|
| Conditions at Accident Site: | VMC | Condition of Light: | Day |
| Observation Facility, Elevation: | KOSA,363 ft msl | Observation Time: | 13:30 Local |
| Distance from Accident Site: | | Temperature/Dew Point: | 18°C /0°C |
| Lowest Cloud Condition: | Clear | Wind Speed/Gusts, Direction: | 4 knots / , 240° |
| Lowest Ceiling: | | Visibility: | |
| Altimeter Setting: | 30.17 inches Hg | Type of Flight Plan Filed: | None |
| Departure Point: | Marietta, TX | Destination: | Texarkana, TX |

Wreckage and Impact Information

| | | | |
|----------------------------|--------|-----------------------------|----------------------------|
| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
| Passenger Injuries: | 4 None | Aircraft Fire: | None |
| Ground Injuries: | | Aircraft Explosion: | None |
| Total Injuries: | 5 None | Latitude, Longitude: | 33.194025,-94.526083 (est) |

Administrative Information

| | |
|--|--|
| Investigator In Charge (IIC): | Aguilera, Jason |
| Additional Participating Persons: | Daniel Montie; FAA FSDO; Irving, TX |
| Investigation Class: | Class 4 |
| Note: | The NTSB did not travel to the scene of this accident. |