



Aviation Investigation Preliminary Report

Location:	Kodiak, AK	Accident Number:	ANC21LA020
Date & Time:	March 2, 2021, 15:39 Local	Registration:	N1767
Aircraft:	ROBINSON HELICOPTER CO R66	Injuries:	1 Fatal
Flight Conducted Under:	Part 91: General aviation - Personal		

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER CO	Registration:	N1767
Model/Series:	R66	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	On file	Operating Certificate(s) Held:	On-demand air taxi (135)

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site:	Unknown	Condition of Light:	Day
Observation Facility, Elevation:	PASO,29 ft msl	Observation Time:	15:23 Local
Distance from Accident Site:	32 Nautical Miles	Temperature/Dew Point:	-3°C /-5°C
Lowest Cloud Condition:		Wind Speed/Gusts, Direction:	4 knots / ,
Lowest Ceiling:	Overcast / 1000 ft AGL	Visibility:	10 miles
Altimeter Setting:	29.16 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	Anchorage, AK (MRI)	Destination:	Kodiak, AK (ADQ)

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	N/A	Aircraft Fire:	Unknown
Ground Injuries:	N/A	Aircraft Explosion:	Unknown
Total Injuries:	1 Fatal	Latitude, Longitude:	58.872527,-152.13761 (est)

Administrative Information

Investigator In Charge (IIC):	Swenson, Eric
Additional Participating Persons:	David Longan; FAA; Juneau, AK Thom Webster; Robinson Helicopter Company; Torrance, CA
Investigation Class:	Class 3
Note:	The NTSB did not travel to the scene of this accident.