

Attachment 5 – Photograph Log
(2 **Pages**)

HWY-00-F-H001 PHOTOGRAPH LOG

HWY-00-F-H001 Photo No. 1 – Right rear of school bus showing impact damage and intrusion.

HWY-00-F-H001 Photo No. 2 – School bus impact and intrusion.

HWY-00-F-H001 Photo No. 3 – Frontal damage of dump truck.

HWY-00-F-H001 Photo No. 4 – Three axle trailer.