

Island Lady Monthly Maintenance Report

DATE: January 2017

Name: William Engineer

Starboard S#9WR01393	3406E Caterpillar Mains	Port S#9Wr01392
----------------------	-------------------------	-----------------

<table style="width: 100%; border-collapse: collapse;"> <tr><td style="border-bottom: 1px solid black;">09/15/2016</td><td>Flush</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Oil Changed</td></tr> <tr><td style="border-bottom: 1px solid black;">1/20/2017</td><td>Fuel Filter</td></tr> <tr><td style="border-bottom: 1px solid black;">09/15/2016</td><td>Heat Exchanger</td></tr> <tr><td style="border-bottom: 1px solid black;">09/15/2016</td><td>AirFilter</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Transmission Fluid</td></tr> <tr><td style="border-bottom: 1px solid black;">10/05/2016</td><td>Thermostat</td></tr> <tr><td style="border-bottom: 1px solid black;">N/A</td><td>Belts</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Battery Water</td></tr> </table>	09/15/2016	Flush	12/08/2016	Oil Changed	1/20/2017	Fuel Filter	09/15/2016	Heat Exchanger	09/15/2016	AirFilter	12/08/2016	Transmission Fluid	10/05/2016	Thermostat	N/A	Belts	12/08/2016	Battery Water	<table style="width: 100%; border-collapse: collapse;"> <tr><td style="border-bottom: 1px solid black;">09/15/2016</td><td>Flush</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Oil Changed</td></tr> <tr><td style="border-bottom: 1px solid black;">1/20/2017</td><td>Fuel Filter</td></tr> <tr><td style="border-bottom: 1px solid black;">09/15/2016</td><td>Heat Exchanger</td></tr> <tr><td style="border-bottom: 1px solid black;">09/15/2016</td><td>AirFilter</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Transmission Fluid</td></tr> <tr><td style="border-bottom: 1px solid black;">10/05/2016</td><td>Thermostat</td></tr> <tr><td style="border-bottom: 1px solid black;">10/05/2016</td><td>Belts</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Battery Water</td></tr> </table>	09/15/2016	Flush	12/08/2016	Oil Changed	1/20/2017	Fuel Filter	09/15/2016	Heat Exchanger	09/15/2016	AirFilter	12/08/2016	Transmission Fluid	10/05/2016	Thermostat	10/05/2016	Belts	12/08/2016	Battery Water
09/15/2016	Flush																																				
12/08/2016	Oil Changed																																				
1/20/2017	Fuel Filter																																				
09/15/2016	Heat Exchanger																																				
09/15/2016	AirFilter																																				
12/08/2016	Transmission Fluid																																				
10/05/2016	Thermostat																																				
N/A	Belts																																				
12/08/2016	Battery Water																																				
09/15/2016	Flush																																				
12/08/2016	Oil Changed																																				
1/20/2017	Fuel Filter																																				
09/15/2016	Heat Exchanger																																				
09/15/2016	AirFilter																																				
12/08/2016	Transmission Fluid																																				
10/05/2016	Thermostat																																				
10/05/2016	Belts																																				
12/08/2016	Battery Water																																				

Starboard Kubota Gen	Generators	Port Kubota Gen V1505
----------------------	------------	-----------------------

<table style="width: 100%; border-collapse: collapse;"> <tr><td colspan="2">M/S#V1902-B-115106</td></tr> <tr><td colspan="2" style="text-align: center;">17KW</td></tr> <tr><td style="border-bottom: 1px solid black;">09/15/2016</td><td>Flush</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Oil Changed</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Fuel Filter</td></tr> <tr><td style="border-bottom: 1px solid black;"></td><td>Heat Exchanger</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>AirFilter</td></tr> <tr><td style="border-bottom: 1px solid black;">N/A</td><td>Thermostat</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Belts</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Battery Water</td></tr> </table>	M/S#V1902-B-115106		17KW		09/15/2016	Flush	12/08/2016	Oil Changed	12/08/2016	Fuel Filter		Heat Exchanger	12/08/2016	AirFilter	N/A	Thermostat	12/08/2016	Belts	12/08/2016	Battery Water	<table style="width: 100%; border-collapse: collapse;"> <tr><td colspan="2">M#V1505-B</td></tr> <tr><td colspan="2" style="text-align: center;">12KW</td></tr> <tr><td style="border-bottom: 1px solid black;">09/15/2016</td><td>Flush</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Oil Changed</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Fuel Filter</td></tr> <tr><td style="border-bottom: 1px solid black;">09/15/2016</td><td>Heat Exchanger</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>AirFilter</td></tr> <tr><td style="border-bottom: 1px solid black;">N/A</td><td>Thermostat</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Belts</td></tr> <tr><td style="border-bottom: 1px solid black;">12/08/2016</td><td>Battery Water</td></tr> </table>	M#V1505-B		12KW		09/15/2016	Flush	12/08/2016	Oil Changed	12/08/2016	Fuel Filter	09/15/2016	Heat Exchanger	12/08/2016	AirFilter	N/A	Thermostat	12/08/2016	Belts	12/08/2016	Battery Water
M/S#V1902-B-115106																																									
17KW																																									
09/15/2016	Flush																																								
12/08/2016	Oil Changed																																								
12/08/2016	Fuel Filter																																								
	Heat Exchanger																																								
12/08/2016	AirFilter																																								
N/A	Thermostat																																								
12/08/2016	Belts																																								
12/08/2016	Battery Water																																								
M#V1505-B																																									
12KW																																									
09/15/2016	Flush																																								
12/08/2016	Oil Changed																																								
12/08/2016	Fuel Filter																																								
09/15/2016	Heat Exchanger																																								
12/08/2016	AirFilter																																								
N/A	Thermostat																																								
12/08/2016	Belts																																								
12/08/2016	Battery Water																																								

--

Notes: Month Of January 2017 On the Island Lady I Couldnt do much, No Funds. Ken and I Replaced Some rotting wood on the back deck. Had Dilon the Deckhand put in new Led lights in both Bathrooms. The Crew Changed the Racor filters once a week due to fungus in the fuel tanks. I was not Present on this Boat in January. Replaced all LightBulbs with led daylighters all around vessel.

August 2016 installed new a/c and a/c pump in lazzerette

December 2016 replaced both alternators on both generators

September 2016 Replaced Raw Water pumps on both generators

September 2016 replaced fresh water Circulating pumps on both Generators

October of 2016 replaced Oil Cooler On Stbd Main 3406E

FEB 09 2017

Island Lady Monthly Maintenance Report

DATE: 02/09/2017

Name: William Engineer

Starboard S#9WR01393	3406E Caterpillar Mains	Port S#9Wr01392
24 volt Dual d8		24 volt Dual d8
<u>09/15/2016</u> Flush		<u>09/15/2016</u> Flush
<u>12/08/2016</u> Oil Changed		<u>12/08/2016</u> Oil Changed
<u>1/20/2017</u> Fuel Filter		<u>1/20/2017</u> Fuel Filter
<u>09/15/2016</u> Heat Exchanger		<u>09/15/2016</u> Heat Exchanger
<u>09/15/2016</u> AirFilter		<u>09/15/2016</u> AirFilter
<u>12/08/2016</u> Transmission Fluid Change		<u>12/08/2016</u> Transmission Fluid Change
<u>10/05/2016</u> Thermostat		<u>10/05/2016</u> Thermostat
<u>N/A</u> Belts		<u>10/05/2016</u> Belts
<u>2/5/2017</u> Battery Water		<u>2/5/2017</u> Battery Water

Starboard Kubota Gen	Generators	Port Kubota Gen V1505
12 Volt		12 volt
<u>09/15/2016</u> Flush		<u>09/15/2016</u> Flush
<u>12/08/2016</u> Oil Changed		<u>12/08/2016</u> Oil Changed
<u>12/08/2016</u> Fuel Filter		<u>12/08/2016</u> Fuel Filter
		<u>09/15/2016</u> Heat Exchanger
<u>12/08/2016</u> AirFilter		<u>12/08/2016</u> AirFilter
<u>NONE</u> Thermostat		<u>NONE</u> Thermostat
<u>12/08/2016</u> Belts		<u>12/08/2016</u> Belts
<u>2/5/2017</u> Battery Water		<u>2/5/2017</u> Battery Water

Notes: In the Month of Febuary on the Island Lady, I removed three speakers off trhe vessel as they were causing Hardcore rusting on the vessel gell coat. I then Cleaned all the rust spots and rust on the windows with Pink Stuff. I added to each Tank Lucas Fuel Treatment on 02/9/17 5pm and biodor-jl fungus killer to all three tanks 2 pm to try and combat the fungus in the fuel tanks that are clogging all the filters weekly. I serviced all the Batterys in the Engine Room and checked water level. I replaced all terminals and cleaned. I also Replaced all the Wooden Battery Boxes in the Engine room with plastic Dual d8 Boxes from west marine. I also Changed all the oil and filters along with all fuel filters. I changed the Generators air filters. Changed out melted fittings on the Saltwater Toilet Pump.

Island Lady Monthly Maintenance Report

DATE: March 2017

Name: William Engineer

Starboard S#9WR01393	3406E Caterpillar Mains	Port S#9Wr01392	
24 volt Dual d8		24 volt Dual d8	
<u>03-10-17</u>	Flush	<u>03-10-17</u>	Flush
<u>03-10-17</u>	Oil Changed	<u>03-10-17</u>	Oil Changed
<u>03-10-17</u>	Fuel Filter	<u>03-10-17</u>	Fuel Filter
<u>03-10-17</u>	Heat Exchanger	<u>03-10-17</u>	Heat Exchanger
<u>09/15/2016</u>	AirFilter	<u>09/15/2016</u>	AirFilter
<u>12/08/2016</u>	Transmission Fluid Change	<u>12/08/2016</u>	Transmission Fluid Change
<u>10/05/2016</u>	Thermostat	<u>10/05/2016</u>	Thermostat
<u>N/A</u>	Belts	<u>10/05/2016</u>	Belts
<u>03-10-17</u>	Battery Water	<u>03-10-17</u>	Battery Water

Starboard Kubota Gen	Generators	Port Kubota Gen V1505	
12 Volt		12 volt	
<u>09/15/2016</u>	Flush	<u>09/15/2016</u>	Flush
<u>03-10-17</u>	Oil Changed	<u>03-10-17</u>	Oil Changed
<u>03-10-17</u>	Fuel Filter	<u>03-10-17</u>	Fuel Filter
<u>N/A</u>	Heat Exchanger	<u>09/15/2016</u>	Heat Exchanger
<u>03-10-17</u>	AirFilter	<u>03-10-17</u>	AirFilter
<u>None</u>	Thermostat	<u>None</u>	Thermostat
<u>12/08/2016</u>	Belts	<u>12/08/2016</u>	Belts
<u>03-10-17</u>	Battery Water	<u>03-10-17</u>	Battery Water

Notes: In the Month of March on the Island Lady, I installed two outdoor marine speakers.

I serviced all the Batterys in the Engine Room and checked water level. Changed a fitting on port shaft seal

I also Changed all the oil and filters along with all fuel filters. I changed the Generators air filters.

Tightened port shaft seal. Stained and polyurythaned the service ladder. Painted: all the decks with non skid Grey Deck Paint and the floors in the bathroom. Installed new Coolant Caps 13 pounders on both gens

to prevent coolant overflow on the wood beneath and added new hose and lowered overflow tanks with clamps on each end to prevent water seapege and gravity feed overflow. Which has produced a positive action and works well 3/10/17 Ordered and installed 22 feet of 8 inch exhust hose and 22 clamps to fix all the water exhaust leaking.

Island Lady Monthly Maintenance Report

DATE: APRIL 2017

Name: William Engineer

Starboard S#9WR01393	3406E Caterpillar Mains	Port S#9Wr01392
24 volt Dual d8		24 volt Dual d8
<u>04-21-17</u> Flush		<u>04-21-17</u> Flush
<u>04-21-17</u> Oil Changed		<u>04-21-17</u> Oil Changed
<u>04-21-17</u> Fuel Filter		<u>04-21-17</u> Fuel Filter
<u>04-21-17</u> Heat Exchanger		<u>04-21-17</u> Heat Exchanger
<u>04-21-17</u> AirFilter		<u>04-21-17</u> AirFilter
<u>12/08/2016</u> Transmission Fluid Change		<u>12/08/2016</u> Transmission Fluid Change
<u>10/05/2016</u> Thermostat		<u>10/05/2016</u> Thermostat
<u>N/A</u> Belts		<u>10/05/2016</u> Belts
<u>04-21-17</u> Battery Water		<u>04-21-17</u> Battery Water

Starboard Kubota Gen	Generators	Port Kubota Gen V1505
12 Volt		12 volt
<u>09/15/2016</u> Flush		<u>09/15/2016</u> Flush
<u>04-21-17</u> Oil Changed		<u>04-21-17</u> Oil Changed
<u>04-21-17</u> Fuel Filter		<u>04-21-17</u> Fuel Filter
<u>04-21-17</u> Heat Exchanger		<u>09/15/2016</u> Heat Exchanger
<u>04-21-17</u> AirFilter		<u>04-21-17</u> AirFilter
<u>NONE</u> Thermostat		<u>NONE</u> Thermostat
<u>12/08/2016</u> Belts		<u>12/08/2016</u> Belts
<u>04-21-17</u> Battery Water		<u>04-21-17</u> Battery Water

Notes: In the Month of APRIL on the Island Lady, stained wood trim around the vessel.

I serviced all the Batterys in the Engine Room and checked water level.

I also Changed all the oil and filters along with all fuel filters. I changed the Generators air filters.

stained and varnished the wing on top of vessel. added chain to fire dampner, engine room, and both hatches up front. added mmsi number to radio and hooked up gps. steering ram rebuilt.

04-21-17 Rebuilt Stbd Main.

Island Lady Monthly Maintenance Report

DATE: May 2017

Name: William Engineer

Starboard S#9WR01393	3406E Caterpillar Mains	Port S#9Wr01392
----------------------	-------------------------	-----------------

24 volt Dual d8		24 volt Dual d8	
<u>05-25-17</u>	Flush	<u>05-25-17</u>	Flush
<u>05-25-17</u>	Oil Changed	<u>05-25-17</u>	Oil Changed
<u>05-25-17</u>	Fuel Filter	<u>05-25-17</u>	Fuel Filter
<u>05-25-17</u>	Heat Exchanger	<u>05-05-17</u>	Heat Exchanger
<u>04-21-17</u>	AirFilter	<u>04-21-17</u>	AirFilter
<u>12/08/2016</u>	Transmission Fluid Change	<u>12/08/2016</u>	Transmission Fluid Change
<u>10/05/2016</u>	Thermostat	<u>10/05/2016</u>	Thermostat
<u>March 2017</u>	Belts	<u>10/05/2016</u>	Belts
<u>05-25-17</u>	Battery Water	<u>05-25-17</u>	Battery Water
<u>5-17-17</u>	Impeller	<u>05-25-17</u>	Impeller

Starboard Kubota Gen	Generators	Port Kubota Gen V1505
----------------------	------------	-----------------------

12 Volt		12 volt	
<u>09/15/2016</u>	Flush	<u>09/15/2016</u>	Flush
<u>05-25-17</u>	Oil Changed	<u>05-25-17</u>	Oil Changed
<u>05-25-17</u>	Fuel Filter	<u>05-25-17</u>	Fuel Filter
<u>09/15/2016</u>	Heat Exchanger	<u>09/15/2016</u>	Heat Exchanger
<u>04-21-17</u>	AirFilter	<u>04-21-17</u>	AirFilter
<u>NONE</u>	Thermostat	<u>NONE</u>	Thermostat
<u>12/08/2016</u>	Belts	<u>12/08/2016</u>	Belts
<u>05-25-17</u>	Battery Water	<u>05-25-17</u>	Battery Water
<u>N/A</u>	Impeller	<u>5-17-17</u>	Impeller

Notes: In the Month of May on the Island Lady, I Replaced two hoses and clamps, A few Gaskets on the

Cooling System, Cleaned the Intercooler and replaced its Gaskets and o-rings on 05-05-2017

Replaced fresh water pump on port main 5-17-17. Replaced raw water pump port main 5-17-17.

Replaced raw water pump on port kubota gen 5-19-17. Changed oil and fuel filters on all motors.

Added lucas oil treatment to all motors. added 2 gallons of lucas fuel treatment in fuel tanks 5-25-17

Replaced an antenna mount for the VHS Radio on top Wing 5-24-17. Serviced all fire extinguishers and fire supression system by Bye-Barker 5-31-17. Had Bilge pump rebuilt with new Impeller from port main

5-31-17. Replaced Port gen Racor Filter Setup.

Island Lady Monthly Maintenance Report

DATE: June 2017

Name: William Engineer

Starboard S#9WR01393	3406E Caterpillar Mains	Port S#9WR01392
----------------------	-------------------------	-----------------

24 volt Dual d8		24 volt Dual d8	
<u>05-25-17</u>	Flush	<u>05-25-17</u>	Flush
<u>06-20-17</u>	Oil Changed	<u>06-20-17</u>	Oil Changed
<u>06-20-17</u>	Fuel Filter	<u>06-20-17</u>	Fuel Filter
<u>05-25-17</u>	Heat Exchanger	<u>05-05-17</u>	Heat Exchanger
<u>4-21-17</u>	AirFilter	<u>4-21-17</u>	AirFilter
<u>12/08/2016</u>	Transmission Fluid Change	<u>12/08/2016</u>	Transmission Fluid Change
<u>10/05/2016</u>	Thermostat	<u>10/05/2016</u>	Thermostat
	Belts	<u>10/05/2016</u>	Belts
<u>06-20-17</u>	Battery Water	<u>06-20-17</u>	Battery Water
<u>5-17-17</u>	Impeller	<u>05-25-17</u>	Impeller

Starboard Kubota Gen	Generators	Port Kubota Gen V1505
----------------------	------------	-----------------------

12 Volt		12 volt	
<u>09/15/2016</u>	Flush	<u>09/15/2016</u>	Flush
<u>06-20-17</u>	Oil Changed	<u>06-20-17</u>	Oil Changed
<u>06-20-17</u>	Fuel Filter	<u>06-20-17</u>	Fuel Filter
<u>09/15/2016</u>	Heat Exchanger	<u>09/15/2016</u>	Heat Exchanger
<u>06-20-17</u>	AirFilter	<u>06-20-17</u>	AirFilter
<u>NOA 2</u>	Thermostat	<u>NOA 2</u>	Thermostat
<u>12/08/2016</u>	Belts	<u>12/08/2016</u>	Belts
<u>05-25-17</u>	Battery Water	<u>05-25-17</u>	Battery Water
	Impeller	<u>5-17-17</u>	Impeller

Notes: Replaced Door Knobs on Restrooms, Added new Restroom Signs to doors. Camera added in bar Area.

Added two gallons of lucas fuel treatment and algae killer to all three fuel tanks. Replaced both a/c filters.

06-20-17 Welded Stbd&Port Main Water Elbows and ReWrapped in Heat Wrap. Cleaned the bilge and wiped down the motors then painted them also oil and fuel changes.

6-21-17 GelCoating and Body Work being done around vessel with cracks. 6-21-17 installed 2 scoop Strainers on the bottom of the vessel Port&Stbd Mains. SCREWED TRIM BACK ON WALL THAT FELL 6-26-17

MOVED LIFEJACKETS INSIDE AND UPDATED SIGNS AND LOCATIONS 152 ADULT 16 CHILDREN.

TOOK OUT WATER LINES IN LAZZ FROM WATER HEATER THAT WE TOOK OUT 6-26-17.

RESTAINED ALL THE WOOD TRIM AROUND THE BOAT 6-24-17. HUNG THE LADDER WITH HOOKS BY THE BRIDGE 6-24-17.

RIPPED OUT CARPET ON TOP DECK AND ROLLED EXTRA TEXTURED GREY DECK PAINT AND WIPED DOWN CHAIRS AND WALL WITH BLEACH 6-24-17.

Island Lady Monthly Maintenance Report

DATE: July 2017

Name: William Engineer

Starboard S#9WR01393	3406E Caterpillar Mains	Port S#9WR01392
----------------------	-------------------------	-----------------

24 volt Dual d8	24 volt Dual d8
<u>05-25-17</u> Flush	<u>05-25-17</u> Flush
<u>06-20-17</u> Oil Changed	<u>06-20-17</u> Oil Changed
<u>06-20-17</u> Fuel Filter	<u>06-20-17</u> Fuel Filter
<u>05-25-17</u> Heat Exchanger	<u>05-05-17</u> Heat Exchanger
<u>4-21-17</u> AirFilter	<u>4-21-17</u> AirFilter
<u>12/08/2016</u> Transmission Fluid Change	<u>12/08/2016</u> Transmission Fluid Change
<u>10/05/2016</u> Thermostat	<u>10/05/2016</u> Thermostat
<u>07/17/17</u> Belts	<u>10/05/2016</u> Belts
<u>7/17/17</u> Battery Water	<u>7/17/17</u> Battery Water
<u>5-17-17</u> Impeller	<u>05-25-17</u> Impeller

Starboard Kubota Gen	Generators	Port Kubota Gen V1505
----------------------	------------	-----------------------

12 Volt	12 volt
<u>09/15/2016</u> Flush	<u>09/15/2016</u> Flush
<u>06-20-17</u> Oil Changed	<u>06-20-17</u> Oil Changed
<u>06-20-17</u> Fuel Filter	<u>06-20-17</u> Fuel Filter
<u>07/17/17</u> Heat Exchanger	<u>09/15/2016</u> Heat Exchanger
<u>06-20-17</u> AirFilter	<u>06-20-17</u> AirFilter
<u>NONE</u> Thermostat	<u>NONE</u> Thermostat
<u>07/17/17</u> Belts	<u>12/08/2016</u> Belts
<u>7/17/17</u> Battery Water	<u>7/17/17</u> Battery Water
<u>07/17/17</u> Impeller	<u>5-17-17</u> Impeller

Notes: Installed New Sea Strainer Stbd Gen, Replaced Impeller and Hose on Stbd Gen.
 Replaced leaking Lazz Exhaust Pipe stbd Main. Replaced Altenator on Stbd Main.
 Did not do oil changes in month of july. Battery Terminals Replaced on all batteries.
 stained some wood trim around vessel.

Island Lady Monthly Maintenance Report

DATE: August 2017

Name: William Engineer

Starboard S#9WR01393	3406E Caterpillar Mains	Port S#9Wr01392
----------------------	-------------------------	-----------------

24 volt Dual d8	24 volt Dual d8
<u>08/25/17</u> Flush	<u>08/25/17</u> Flush
<u>06-20-17</u> Oil Changed	<u>06-20-17</u> Oil Changed
<u>06-20-17</u> Fuel Filter	<u>06-20-17</u> Fuel Filter
<u>08/25/17</u> Heat Exchanger	<u>08/25/17</u> Heat Exchanger
<u>04-21-17</u> AirFilter	<u>04-21-17</u> AirFilter
<u>12/08/2016</u> Transmission Fluid Change	<u>12/08/2016</u> Transmission Fluid Change
<u>08/25/17</u> Thermostat	<u>08/25/17</u> Thermostat
<u>07/17/17</u> Belts	<u>10/05/2016</u> Belts
<u>7/17/17</u> Battery Water	<u>7/17/17</u> Battery Water
<u>5-17-17</u> Impeller	<u>05-25-17</u> Impeller <u>05-25-17</u> Impeller Bilge

Starboard Kubota Gen	Generators	Port Kubota Gen V1505
----------------------	------------	-----------------------

12 Volt	12 volt
<u>09/15/2016</u> Flush	<u>09/15/2016</u> Flush
<u>06-20-17</u> Oil Changed	<u>06-20-17</u> Oil Changed
<u>06-20-17</u> Fuel Filter	<u>06-20-17</u> Fuel Filter
<u>07/17/17</u> Heat Exchanger	<u>09/15/2016</u> Heat Exchanger
<u>06-20-17</u> AirFilter	<u>06-20-17</u> AirFilter
Thermostat	Thermostat
<u>07/17/17</u> Belts	<u>12/08/2016</u> Belts
<u>7/17/17</u> Battery Water	<u>7/17/17</u> Battery Water
<u>07/17/17</u> Impeller	<u>5-17-17</u> Impeller

Notes: Installed Battery Chargers on Both Mains. Installed Blower Ventilation to a breaker in engine room.
 Took floor and ladders out of engine room, Sanded, Stained Dark walnut to hide oil stains, 2 Coats of Polyurithane.
 Cleaned Turbos both mains 8/17/17. Cleaned center bilge in engine room full of sand and oil, then laid newly stained floor down. New Fresh Water Pump Installed in Lazz. New sea strainer installed bow a/c.
 New Alternator Installed on stbd Gen. Biobor algae killing treatment added to all fuel tanks.
 Installed new shore Power hook up to front of vessel. Also new S.P connector on dock.
 Replaced Thermostats for 185Degrees and cleaned heat exchangers p&s Main.

Island Lady Monthly Maintenance Report

DATE: September 2017

Name: William Engineer

Starboard S#9WR01393	3406E Caterpillar Mains	Port S#9Wr01392
----------------------	-------------------------	-----------------

24 volt Dual d8		24 volt Dual d8	
<u>08/25/17</u>	Flush	<u>08/25/17</u>	Flush
<u>09/04/2017</u>	Oil Changed	<u>09/04/2017</u>	Oil Changed
<u>09/04/2017</u>	Fuel Filter	<u>09/04/2017</u>	Fuel Filter
<u>08/25/17</u>	Heat Exchanger	<u>08/25/17</u>	Heat Exchanger
<u>04-21-17</u>	AirFilter	<u>04-21-17</u>	AirFilter
<u>12/08/2016</u>	Transmission Fluid Change	<u>12/08/2016</u>	Transmission Fluid Change
<u>08/25/17</u>	Thermostat	<u>08/25/17</u>	Thermostat
<u>07/17/17</u>	Belts	<u>10/05/2016</u>	Belts
<u>7/17/17</u>	Battery Water	<u>7/17/17</u>	Battery Water
<u>5-17-17</u>	Impeller	<u>05-25-17</u>	Impeller
		<u>05-25-17</u>	Impeller Bilge

Starboard Kubota Gen	Generators	Port Kubota Gen V1505
----------------------	------------	-----------------------

M/S#V1902-B-115106	12volt	M#V1505-B	
17KW		12KW	
<u>09/15/2016</u>	Flush	<u>09/15/2016</u>	Flush
<u>09/04/2017</u>	Oil Changed	<u>09/04/2017</u>	Oil Changed
<u>09/04/2017</u>	Fuel Filter	<u>09/04/2017</u>	Fuel Filter
<u>07/17/17</u>	Heat Exchanger	<u>09/04/2017</u>	Heat Exchanger
<u>06-20-17</u>	AirFilter	<u>06-20-17</u>	AirFilter
<u>None</u>	Thermostat	<u>None</u>	Thermostat
<u>07/17/17</u>	Belts	<u>12/08/2016</u>	Belts
<u>09/04/2017</u>	Battery Water	<u>09/04/2017</u>	Battery Water
<u>07/17/17</u>	impeller	<u>09/04/2017</u>	Impeller

Notes: MONTH OF SEPTEMBER 2017, I CHANGED OIL AND OIL FILTERS ON ALL MOTORS, AND RACOR FILTERS AS WELL. CLEANED PORT GEN HEAT EXCHANGER AND REPLACED IMPELLER . IT NEEDS A SEA STRAINER . INSTALLED MARINE BATTERY CHARGER ON GENERATOR BANKS. UNHOOKED ALTERNATORS AND WIRED ALL BATTERY CHARGERS TO ONE BREAKER. REPLACED TOILET HANDLE. Did not Replace Primary Fuel Filters Stained some floor and walls in Engine room.

Island Lady Monthly Maintenance Report

DATE: October 2017

Name: William Engineer

Starboard S#9WR01393	3406E Caterpillar Mains	Port S#9WR01392
----------------------	-------------------------	-----------------

24 volt Dual d8		24 volt Dual d8	
<u>08/25/17</u>	Flush	<u>08/25/17</u>	Flush
<u>09/04/2017</u>	Oil Changed	<u>09/04/2017</u>	Oil Changed
<u>10/13/17</u>	Fuel Filter	<u>10/13/17</u>	Fuel Filter
<u>08/25/17</u>	Heat Exchanger	<u>08/25/17</u>	Heat Exchanger
<u>04-21-17</u>	AirFilter	<u>04-21-17</u>	AirFilter
<u>12/08/2016</u>	Transmission Fluid Change	<u>12/08/2016</u>	Transmission Fluid Change
<u>08/25/17</u>	Thermostat	<u>08/25/17</u>	Thermostat
<u>07/17/17</u>	Belts	<u>10/05/2016</u>	Belts
<u>7/17/17</u>	Battery Water	<u>7/17/17</u>	Battery Water
<u>5-17-17</u>	Impeller	<u>05-25-17</u>	Impeller
		<u>05-25-17</u>	Impeller Bilge

Starboard Kubota Gen	Generators	Port Kubota Gen V1505
----------------------	------------	-----------------------

M/S#V1902-B-115106 17KW	12volt	M#V1505-B 12KW	
<u>09/15/2016</u>	Flush	<u>09/15/2016</u>	Flush
<u>09/04/2017</u>	Oil Changed	<u>09/04/2017</u>	Oil Changed
<u>09/04/2017</u>	Fuel Filter	<u>09/04/2017</u>	Fuel Filter
<u>07/17/17</u>	Heat Exchanger	<u>09/04/2017</u>	Heat Exchanger
<u>06-20-17</u>	AirFilter	<u>06-20-17</u>	AirFilter
<u>none</u>	Thermostat	<u>none</u>	Thermostat
<u>07/17/17</u>	Belts	<u>12/08/2016</u>	Belts
<u>09/04/2017</u>	Battery Water	<u>09/04/2017</u>	Battery Water
<u>07/17/17</u>	Impeller	<u>09/04/2017</u>	Impeller

--

Notes: Replaced ladder and floor back of engine room, Sanded, Stained, Varnished. Installed Cameras all around Vessel. 3 gallons lucas fuel treatment 10/13/17 and biobor algae treatment in all 3 fuel tanks.

No oil changes this month. Emptied a/c condensation stern a/c. Replaced all Fuel and Racor Filters.

Replaced h2o Filter.
