



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: STB.043.01.001 - TURBINE, HP
Performed Function: 612.001.010 - TURBINE, HP UNIT

Component											
Done date	Work Order	Job Code	Job Title							Hours	Spares
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
06.12.2013	E110639		I-E7020		MN ENG HS COUPLING	I-E7020 - MN ENG HS COUPLING INSPECTION				0.00	
612.001.010 - TURBINE, HP UNIT		1	INSPECTION	EEFCHIEF		Planned Preventative	<input type="checkbox"/>	12 Month(s)	18	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: HUL.100.01.001 - HULL, UNDERWATER
Performed Function: 279.020.000 - HULL BELOW WATERLINE

Component											
Done date	Work Order	Job Code	Job Title							Hours	Spares
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
15.12.2013	E120026		W-E4015		HULL CLEAN	W-E4015 - HULL CLEAN				0.00	
279.020.000 - HULL BELOW WATERLINE		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	3 Month(s)	19	Undefined	
18.12.2013	E140057		W-E4015		HULL CLEAN	W-E4015 - HULL CLEAN				0.00	
279.020.000 - HULL BELOW WATERLINE		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	3 Month(s)	0	Undefined	
18.12.2013	E140060		W-E4015		HULL CLEAN	W-E4015 - HULL CLEAN				0.00	
279.020.000 - HULL BELOW WATERLINE		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	3 Month(s)	0	Undefined	
18.12.2013	E140042		W-E4015		HULL CLEAN	W-E4015 - HULL CLEAN				0.00	
279.020.000 - HULL BELOW WATERLINE		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	3 Month(s)	0	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: PRO.125.02.001 - PROPELLER
Performed Function: 631.001.000 - PROPULSION PROPELLER

Component											
Done date	Work Order	Job Code	Job Title							Hours	Spares
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
15.12.2013	E120025		W-E4020		PROPELLAR POLISH	W-E4020 - PROPELLAR POLISH				0.00	
631.001.000 - PROPULSION PROPELLER		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	3 Month(s)	19	Undefined	
18.12.2013	E140043		W-E4020		PROPELLAR POLISH	W-E4020 - PROPELLAR POLISH				0.00	
631.001.000 - PROPULSION PROPELLER		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	3 Month(s)	0	Undefined	
18.12.2013	E140056		W-E4020		PROPELLAR POLISH	W-E4020 - PROPELLAR POLISH				0.00	
631.001.000 - PROPULSION PROPELLER		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	3 Month(s)	0	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: PUR.059.03.001 - OILY WATER SEPERATOR
Performed Function: 803.025.002 - SEPARATOR, OILY WATER

Component											
Done date	Work Order	Job Code	Job Title						Hours	Spares	
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
18.12.2013	E140031		W-E7005		OWS OIL DETECTOR CLEAN	W-E7005 - OWS OIL DETECTOR CLEAN			0.00		
803.025.002 - SEPARATOR, OILY WATER		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	12 Month(s)	0	Undefined	
18.12.2013	E120296		W-E7005		OWS OIL DETECTOR CLEAN	W-E7005 - OWS OIL DETECTOR CLEAN			0.00		
803.025.002 - SEPARATOR, OILY WATER		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	12 Month(s)	10	Undefined	
18.12.2013	E120295		R-E7020		OWS REPLACE / REGENERATE FILTER MEDIA	R-E7020 - OWS REPLACE / REGENERATE FILTER MEDIA			0.00		
803.025.002 - SEPARATOR, OILY WATER		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	12 Month(s)	10	Undefined	
18.12.2013	E140023		R-E7020		OWS REPLACE / REGENERATE FILTER MEDIA	R-E7020 - OWS REPLACE / REGENERATE FILTER MEDIA			0.00		
803.025.002 - SEPARATOR, OILY WATER		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	12 Month(s)	0	Undefined	
18.12.2013	E140032		W-E7010		OWS OIL DESCALER BACK FLUSH	W-E7010 - OWS OIL DESCALER BACK FLUSH			0.00		
803.025.002 - SEPARATOR, OILY WATER		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	12 Month(s)	0	Undefined	
18.12.2013	E120298		C-E7005		OWS ANNUAL CHECKS	C-E7005 - OWS ANNUAL CHECKS			0.00		
803.025.002 - SEPARATOR, OILY WATER		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	12 Month(s)	10	Undefined	
18.12.2013	E140020		C-E7005		OWS ANNUAL CHECKS	C-E7005 - OWS ANNUAL CHECKS			0.00		
803.025.002 - SEPARATOR, OILY WATER		1		EEFCHIEF		Planned Preventative	<input type="checkbox"/>	12 Month(s)	0	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: BAT.283.01.001 - BATTERIES, STORAGE
Performed Function: 866.001.001 - STORAGE BATTERIES

Component											
Done date	Work Order	Job Code	Job Title							Hours	Spares
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
27.10.2013	E140611		C-E1005		STORAGE BATTERY CHECK	C-E1005 - STORAGE BATTERY CHECK				0.00	
866.001.001 - STORAGE BATTERIES		1		EEFFENG		Planned Preventative	<input type="checkbox"/>	1 Week(s)	0	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: FDT.281.01.001 - DETECTOR
Performed Function:

Component										
Done date	Work Order	Job Code	Job Title						Hours	Spares
Function	Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
30.09.2013	E140008			Unplanned Maintenance				0.00		
			EEFCHIEF	Material Failure	Unplanned Corrective	<input checked="" type="checkbox"/>	0 Month(s)	0	Undefined	
TOTAL:								0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: ALM.277.01.001 - DETECTOR, OWS OIL CONTENT
Performed Function: 797.024.011 - OWS OIL CONTENT DETECTOR

Component											
Done date	Work Order	Job Code	Job Title							Hours	Spares
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
26.12.2013	E120021	A-E4005	TEST EQUIPMENT		A-E4005 - TEST EQUIPMENT CALIBRATION					0.00	
797.024.011 - OWS OIL CONTENT DETECTOR		1	CALIBRATION Class Survey (Others)	EEFCHIEF		Planned Preventative	<input type="checkbox"/>	12 Month(s)	13	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: PMP.203.02.002 - PUMP, FO SERVICE
Performed Function: 703.003.002 - PUMP, FO.SERVICE, NO.2

Component											
Done date	Work Order	Job Code	Job Title							Hours	Spares
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
04.02.2013	E140929		L-E3030		COUPLING LUBRICATION	L-E3030 - COUPLING LUBRICATION				0.00	
703.003.002 - PUMP, FO.SERVICE, NO.2		1		EEFFENG	Normal Wear and Tear	Planned Preventative	<input type="checkbox"/>	2 Month(s)	0	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: ALM.138.01.001 - ALARM SYSTEM, GENERAL
Performed Function: 425.300.001 - GENERAL ALARM SYSTEM

Component											
Done date	Work Order	Job Code	Job Title							Hours	Spares
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
09.12.2013	D120037	T-D7025	GENERAL ALARM BELL TEST							0.00	
425.300.001 - GENERAL ALARM SYSTEM		1	Class Survey (Others)	EEFCHIEF		Inspection/Function Test	<input type="checkbox"/>	12 Month(s)	10	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: LSE.999.03.001 - LIFEBOAT
Performed Function: 501.001.001 - LIFEBOAT, PORT

Component											
Done date	Work Order	Job Code	Job Title							Hours	Spares
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
27.01.2013	D140323		T-D7015		LIFEBOAT, PORT WEIGHT TEST	T-D7015 - LIFEBOAT, PORT WEIGHT TEST				0.00	
501.001.001 - LIFEBOAT, PORT		1	Class Survey (Others)	DEFFOFF		Inspection/Function Test	<input type="checkbox"/>	12 Month(s)	0	Undefined	
28.09.2013	D120348		I-D7015		LIFEBOAT PORT INSPECTION, YEARLY	I-D7015 - LIFEBOAT PORT INSPECTION, YEARLY				0.00	
501.001.001 - LIFEBOAT, PORT		1	YEARLY Class Survey (Others)	DEFFOFF		Inspection/Function Test	<input type="checkbox"/>	12 Month(s)	44	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: LSE.999.03.002 - LIFEBOAT
Performed Function: 501.001.002 - LIFEBOAT, STBD.

Component											
Done date	Work Order	Job Code	Job Title							Hours	Spares
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
27.01.2013	D140322	T-D7020	LIFEBOAT, STBD WEIGHT TEST T-D7020 - LIFEBOAT, STBD WEIGHT TEST							0.00	
501.001.002 - LIFEBOAT, STBD.		1	Class Survey (Others)	DEFFOFF		Inspection/Function Test	<input type="checkbox"/>	12 Month(s)	0	Undefined	
28.09.2013	D120035	I-D7010	LIFEBOAT STBD INSPECTION, I-D7010 - LIFEBOAT STBD INSPECTION, YEARLY							0.00	
501.001.002 - LIFEBOAT, STBD.		1	YEARLY Class Survey (Others)	DEFFOFF		Inspection/Function Test	<input type="checkbox"/>	12 Month(s)	7	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: BLR.226.02.001 - BOILER, MAIN
Performed Function: 641.001.300 - MAIN BOILER NO.1 (STBD)

Component											
Done date	Work Order	Job Code	Job Title							Hours	Spares
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
20.12.2013	E120276		I-258		BOILER, INSPECTION	I-258 - BOILER, INSPECTION				0.00	
641.001.300 - MAIN BOILER NO.1 (STBD)		1	Condition Survey	EEFCHIEF	Normal Wear and Tear	Planned Preventative	<input type="checkbox"/>	12 Month(s)	10	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: FFE.999.03.001 - SPRINKLER SYSTEM
Performed Function: 813.005.002 - DECK FIRE SPRINKLER SYSTEM

Component											
Done date	Work Order	Job Code	Job Title							Hours	Spares
Function		Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
18.10.2013	D120036	T-D7040	SPRINKLER SYSTEM TEST			T-D7040 - SPRINKLER SYSTEM TEST				0.00	
813.005.002 - DECK FIRE SPRINKLER SYSTEM		1	Class Survey (Others)	EEFCHIEF		Inspection/Function Test	<input type="checkbox"/>	12 Month(s)	8	Undefined	
TOTAL:									0.00		



MAINTENANCE DONE

El Faro/Engine/Deck

Component From: ALM.138.01.001
Component Name From: ALARM SYSTEM, GENERAL
Component Type From:
Date Done From: 1/27/2013
Job Class From:
Vendor Code From:
Maker Code From: 01331

To: STB.043.01.001
To: TURBINE, HP
To: SUNN DWG# 674-921-9,11,13
To: 12/26/2013
To:
To:
To: 11029

Component: PMP.249.02.002 - PUMP, MAIN CIRC
Performed Function: 721.005.002 - PUMP, MAIN CIRCULATING NO.2

Component										
Done date	Work Order	Job Code	Job Title						Hours	Spares
Function	Rev.	Type	Rep. By	Cause	Class	Unexp.	Frequency	Overdue	Job State	
19.12.2013	E150686			Replace Discharge Expansion Joint				0.00		
721.005.002 - PUMP, MAIN CIRCULATING NO.2			EEFCHIEF	Normal Wear and Tear	Planned Corrective	<input checked="" type="checkbox"/>	0 Month(s)	0	Undefined	
TOTAL:								0.00		