

COMPACT SEAL SERVICE REPORT

KEMEL USA INC 366 Fifth Avenue, Suite 712 New York, NY 10001

TEL: +1 212 967 5575 FAX: +1 212 967 6966

WEB: www.kemelusa.com

Vessel Name		KEMEL Rep		WEAR DOWN RECORD			CENTERING		Clearance of Liner			
	El Faro	De	on Anderso	DATE TOP BOT			RECORD AFT		to Seal Housing (T) Location AFT			
Owner Name	::	Service Per	Service Period:			LAST 27-Jan-11			Eccentricity	.011"	тор	3.5
TOTE	E / Sea Star	15-Dec-13	3 TO 2	O 28-Dec-13		BEFORE 12/16 AFTER 27-Dec-13		107.0 106.7 E	FWD Eccentricity		Bottom PORT	2.5 3.0
Location:	Freeport	Shipyard:	Gl	GBSY		COMMENTS:			FWD Squareness		Starboard	3.0
Seal Size:	CX 750	Serial No.	Serial No. Stru			Seal overhaul with tail shaft withdrawn.						
D is not taken.	#1 #2 #3 # B C D X type seal, measuremen All measurments to cent Record groove width and heet.	Stern Tube Lub	bricant			ST7	7					
# SEA	LING RING CONI	Liner Machining Data										
1 normal wear				n) OLD n fkm		New Liner Diameter D1						
2 normal wear 3 embedded white metal					f4 f4	Machined Liner Diameter —		Г)4)2 7	750.21		mm
35								- L	05			
<u>4</u> <u>5</u>				+		Date Machined, Location		n	Machine polish only			′
AFT Liner wear FWD Liner Seal # Distance Width Depth Seal # Distance Wid						KEMEL Signature						Pate
Seal # Distar		Seal # Distan 4 F	ce Width	Dept	:h	Customer Name/Ti	tle					Date
2 B on		5 E										
3 C liner 3S D		Net Yes	Z Dimen		'mm	Customer Signatu	ıre					