


inboard
face Port Planking
under channel



#2 Port Planking
under channel






#2 Port Planking Under chancel

Port Planking Under chancel



#2 Port Plank 1
under charnel

[Illegible text on background label]






#2 Port Planking
under channel



inboard
Port Planking
under channel










Wood 217 (10/11)
Fall 1961



2m Face
Port Plank
under channel





172
Rustic
10/10/24

P-1
Rustic
10/10/24







#2 Port Plank
under chertel

#2 Port Planking
under channel 1

inboard
face
Port Planking
under channel 1



inboard
face

Port Planking
under channel

#2 Port Planking
under channel



inboard
Purcell

Port Plankings
under channel

#2 Port Plankings
under channel

