



SERVICE REPORT

Service report

Name of vessel: Caribbean Fantasy

Date: 04-05-2017

Port of Freeport Bahamas

**During inspection onboard the vessel above, we found the following item either
In need of repairs or replacement(s)**

MAIN CO2 ROOM

All Co2 Cylinders were check with liquid level according to the list bellow

We found all Cylinder totally empty, need to be refill

N0.	Serial No.	Cap.	Last-Hydro
1	99A628/065	45kg	05/2016
2	99A628/029	45kg	05/2016
3	99A628/012	45kg	05/2016
4	99A628/040	45kg	05/2016
5	99A628/199	45kg	05/2016
6	99A628/083	45kg	05/2016
7	99A628/153	45kg	05/2016
8	99A628/026	45kg	05/2016
9	99A628/076	45kg	05/2016
10	99A628/138	45kg	05/2016
11	99A628/033	45kg	11/1999
12	99A628/095	45kg	11/1999
13	99A628/166	45kg	11/1999
14	99A628/150	45kg	11/1999
15	99A628/104	45kg	11/1999
16	99A628/070	45kg	11/1999
17	99A628/078	45kg	11/1999
18	99A628/191	45kg	11/1999
19	99A628/091	45kg	11/1999
20	99A628/085	45kg	11/1999
21	99A628/074	45kg	11/1999
22	99A628/072	45kg	11/1999
23	99A628/068	45kg	11/1999



AH MARINE
SAFETY & FIRE

24	99A628/071	45kg	11/1999
25	99A628/087	45kg	11/1999
26	99A628/089	45kg	11/1999
27	99A628/039	45kg	11/1999
28	99A628/073	45kg	11/1999
29	99A628/105	45kg	11/1999
30	99A628/141	45kg	11/1999
31	99A628/099	45kg	11/1999
32	99A628/152	45kg	11/1999
33	99A628/188	45kg	11/1999
34	99A628/187	45kg	11/1999
35	99A628/080	45kg	11/1999
36	99A628/036	45kg	11/1999
37	99A628/169	45kg	11/1999
38	99A628/156	45kg	11/1999
39	99A628/160	45kg	11/1999
40	99A628/025	45kg	11/1999
41	99A628/096	45kg	11/1999
42	99A628/158	45kg	11/1999
43	99A628/048	45kg	11/1999
44	99A628/043	45kg	11/1999
45	99A628/200	45kg	11/1999
46	99A628/092	45kg	11/1999
47	99A628/069	45kg	11/1999
48	99A628/001	45kg	11/1999
49	99A628/038	45kg	11/1999
50	99A628/027	45kg	11/1999
51	99A628/147	45kg	11/1999
52	99A628/149	45kg	11/1999
53	99A628/075	45kg	11/1999
54	99A628/045	45kg	11/1999
55	99A628/186	45kg	11/1999
56	99A628/098	45kg	11/1999
57	99A628/190	45kg	11/1999
58	99A628/049	45kg	11/1999
59	99A628/148	45kg	11/1999
60	99A628/157	45kg	11/1999
61	99A628/159	45kg	11/1999
62	99A628/090	45kg	11/1999
63	99A628/197	45kg	11/1999
64	99A628/142	45kg	11/1999
65	99A628/023	45kg	11/1999
66	99A628/185	45kg	11/1999
67	99A628/077	45kg	11/1999
68	99A628/084	45kg	11/1999



AH MARINE
SAFETY & FIRE

69	99A628/004	45kg	11/1999
70	99A628/067	45kg	11/1999
71	99A628/032	45kg	11/1999
72	99A628/189	45kg	11/1999
73	99A628/196	45kg	11/1999
74	99A628/005	45kg	11/1999
75	99A628/145	45kg	11/1999
76	99A628/139	45kg	11/1999
77	99A628/198	45kg	11/1999
78	99A628/082	45kg	11/1999
79	99A628/031	45kg	11/1999
80	99A628/086	45kg	11/1999
81	99A628/154	45kg	11/1999
82	99A628/194	45kg	11/1999
83	99A628/093	45kg	11/1999
84	99A628/081	45kg	11/1999
85	99A628/131	45kg	11/1999
86	99A628/141	45kg	11/1999
87	99A628/079	4.7kg	11/1999
88	99A628/197	45kg	11/1999
89	99A628/008	45kg	11/1999
90	99A628/192	45kg	11/1999
91	99A628/140	45kg	11/1999
92	99A628/168	45kg	11/1999
93	99A628/165	45kg	11/1999
94	99A628/044	45kg	11/1999
95	99A628/034	45kg	11/1999
96	99A628/042	45kg	11/1999
97	99A628/163	45kg	11/1999
98	99A628/193	45kg	11/1999
99	99A628/050	45kg	11/1999
100	99A628/151	45kg	11/1999
101	99A628/002	45kg	11/1999
102	99A628/164	45kg	11/1999
103	99A628/030	45kg	11/1999
104	99A628/144	45kg	11/1999
105	99A628/047	45kg	11/1999
106	99A628/195	45kg	11/1999
107	99A628/035	45kg	11/1999
108	99A628/024	45kg	11/1999
109	99A628/046	45kg	11/1999
110	99A628/170	45kg	11/1999