


Specialist's Report – Attachment 1

ATC Radar Graphics

AIR TRAFFIC CONTROL

CEN18FA053






Figure 2. Radar flight track of N761YZ overlaid on satellite imagery with accident site and airport of intended emergency landing illustrated.

