



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Washington, D.C. 20594

April 22, 2016

Attachment 3 – Radar Plots

AIR TRAFFIC CONTROL SPECIALIST'S REPORT


CEN15FA190

Prepared by
NATIONAL TRANSPORTATION SAFETY BOARD
Office of Aviation Safety (AS-30)
Air Traffic Investigations

NTSB Investigation Number
CEN15FA190

Attachment 3: Radar Plot - Peoria ASR-11
Figure 1 of 3

B. SOPER APRIL, 2016




N789UP Accident Location
40:29.76 N Latitude
088:51.48 W Longitude

Prepared by
NATIONAL TRANSPORTATION SAFETY BOARD
Office of Aviation Safety (AS-30)
Air Traffic Investigations

NTSB Investigation Number
CEN15FA190

Attachment 3: Radar Plot - Champaign ASR-11
Figure 2 of 3

B. SOPER APRIL, 2016



Prepared by
NATIONAL TRANSPORTATION SAFETY BOARD
Office of Aviation Safety (AS-30)
Air Traffic Investigations

NTSB Investigation Number
CEN15FA190

Attachment 3: Radar Plot - Final Segment
Figure 3 of 3

B. SOPER APRIL, 2016



N789UP Accident Location
40:29.76 N Latitude
088:51.48 W Longitude