



Photo 1 – View of left wing and wing strut damage (photo courtesy of the Pilot)