



Photo 1 – Aerial view of the airstrip and the airplane (courtesy of Lane Aviation, Inc.).



Photo 2 – Aerial view of the airstrip and the airplane (courtesy of Lane Aviation, Inc.).



Photo 3 – View of the airplane after it impacted a perimeter fence (courtesy of Lane Aviation, Inc.).



Photo 4 – View of the airplane after it impacted a perimeter fence (courtesy of Lane Aviation, Inc.).



Photo 5 – View of the damaged engine mount (courtesy of Lane Aviation, Inc.).



Photo 6 – View of the damaged fuselage (courtesy of Lane Aviation, Inc.).



Photo 7 – View of the damaged right aileron (courtesy of Lane Aviation, Inc.).