



Photo 1 – Map showing the location of Merrill Pass (courtesy of vfrmap.com).



Photo 2 – Aerial view of the wreckage (courtesy of the NTSB).



Photo 3 – View of the empennage and the right wing (courtesy of the NTSB).



Photo 4 – View of the left wing and the main landing gear (courtesy of the NTSB).