



**Photo 1 – View towards the approach end of the airstrip (FAA photo)**



**Photo 2 – View towards the departure end of the airstrip and the overturned airplane (FAA photo)**






**Photo 3 – Propeller strike marks (FAA photo)**





**Photo 4 – Frontal damage to N7684D (FAA photo)**





**Photo 5 – Crush damage to vertical stabilizer (FAA photo)**