



Photo 1 – Forward View of Wreckage (Courtesy of FAA)



Photo 2 – Right Wing Damage (Courtesy of FAA)



Photo 3 – Firewall Damage (Courtesy of FAA)