



Photo 1 – View of damaged upper and lower right wings of N68117 (photo courtesy of the FAA)



Photo 2 – View of damaged firewall of N73529 (photo courtesy of the FAA)