

Photo 1 – View of airplane floating in the water




Photo 2 – View showing two infant vests in center of picture



Photo 3 – Life vest cut to remove



Photo 4 – Life vest was cut at clinic



Photo 5 – Infant life vest for under 35 pounds



Photo 6 – Airplane salvage after 7 days in ocean




Photo 7 – View of wreckage on salvage boat



Photo 8 – View showing engine was found separated




Photo 9 – View of engine spinner