



**Photo 1 – View of the cove, looking north near the accident site.**



**Photo 2 – View of the accident site.**



**Photo 3 - View of the accident site.**



**Photo 4 - View of the accident site.**



**Photo 5 – View of the cove looking south.**



**Photo 6 - Left Wing**



**Photo 7 – Right Wing**



**Photo 8 – Right wing impact mark**





**Photo 9 – Recovered wreckage.**



**Photo 10 - Recovered wreckage.**



**Photo 11 - Recovered wreckage.**



**Photo 12 – View of the propeller that was embedded within the sea wing.**



**Photo 13 - View of the propeller that was embedded within the sea wing.**



**Photo 14 - Parachute Deployment Handle – At the accident site.**