



**Photo 1 – View of airplane after impact with trees (Photo courtesy of the FAA)**



**Photo 2 – View of damaged left wing spar (Photo courtesy of the FAA)**